

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002415/BTY3N2**Date:** 28/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00200512100

Claimant Vehicle No : SMZ8484T **Insured Vehicle No :** SGV2812L

Date of Loss: 12/03/2022 Nature of Claim: TP Claim No: SNM22D201779/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ8484T**

Make & Model: MERCEDES-BENZ E200, 2.0 (A) Engine No: 27186030008808

Reg. Date: 29/12/2009 (Man. Year: 2009) Chassis No: WDD2120482A097357

Colour: Silver Odometer: 147195 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18

Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm

Front Right Side: Pirelli 4 mm Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,311.86	6,292.79	12,019.07	65.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,270.00	2,760.00	68.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,341.86	7,562.79	14,779.07	66.15
Approved Total (Overridden) (\$\$)		6,050.00		
(\$\$)	22,341.86	6,050.00	16,291.86	72.92
+ GST 7.00/7.00% (\$\$)	1,563.93	423.50	1,140.43	72.92
Nett Amount (\$\$)	23,905.79	6,473.50	17,432.29	72.92

INSPECTION

Date of Assignment: 15/03/2022

Date Inspected: 16/03/2022 Inspected At: Bifront Auto Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Mar 2022)
Parts:	M1-COUPE	MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ8484T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	1,360.95 FL	*1,360.95 FL
2	1		*FRONT BUMPER TOP SEAL	Not Necessary	43.55 FL	*- FL
3	1		*FRONT BUMPER CLIPS	Necessary	70.00 FL	*50.00 FL
4	1		*FRONT BUMPER RH SIDE SENSOR	Short Circuit	217.55 FL	*100.00 FL
5	1		*FRONT BUMPER RH SENSOR	Not Damaged	217.55 FL	*- FL
6	6		*FRONT BUMPER DISTANCE SENSOR RUBBER SEALS	Necessary	57.78 FL	*57.78 FL
7	1		*FRONT BUMPER DISTANCE SENSOR WIRE HARNESS	Not Damaged	351.20 FL	*- FL
8	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	63.94 FL	*38.00 FL
9	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	63.94 FL	*30.00 FL
10	1		*FRONT BUMPER CENTRE BRACKET	Not Damaged	89.33 FL	*- FL
11	1		*FRONT BUMPER RH LOWER CHROME MOULDING	Cut	68.30 FL	*68.30 FL
12	1		*FRONT BUMPER RH LED LAMP	Cut	487.91 FL	*410.00 FL
13	1		*FRONT BUMPER RH LED LAMP CHROME MOULDING	Cut	159.30 FL	*159.30 FL
14	1		*FRONT BUMPER RH LED GARNISH	Broken	78.30 FL	*78.30 FL
15	1		*FRONT BUMPER RH INNER SPONGE	Broken	72.20 FL	*72.20 FL
16	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	628.10 FL	*- FL
17	1		*LH HEADLAMP ASSY	Not Damaged	1,180.00 FL	*- FL
18	1		*RH HEADLAMP ASSY	Cut	1,180.00 FL	*1,180.00 FL
19	1		*RH HEADLAMP BRACKET	No such part	53.05 FL	*- FL
20	1		*RH FRONT FENDER	Dented	951.46 FL	*951.46 FL
21	1		*RH FRONT FENDER SPLASH SHIELD	Not Damaged	199.30 FL	*- FL
22	1		*SET RH FRONT FENDER SPLASH SHIELD CLIPS	Not Necessary	50.00 FL	*- FL
23	1		*RH FRONT FENDER EMBLEM	Necessary	55.70 FL	*55.70 FL
24	1		*SUPPORT PANEL	Not Damaged	989.30 FL	*- FL
25	1		*FRONT GRILLE ASSY	Broken	1,067.40 FL	*695.00 FL
26	1		*PASSENGER HEAD REST	Not Damaged	1,744.90 FL	*- FL
27	1		*PASSENGER SEAT BELT	Not Damaged	934.50 FL	*- FL
28	1		*PASSENGER SEAT BELT BUCKLE	Not Damaged	214.06 FL	*- FL
29	1		*DRIVER HEAD REST	Not Damaged	1,067.40 FL	*- FL
30	1		*DRIVER SEAT BELT	Not Damaged	934.50 FL	*- FL
31	1		*DRIVER SEAT BELT BUCKLE	Not Damaged	214.06 FL	*- FL
32	1		*FRONT RH AIRBAG SENSOR	Not Damaged	231.11 FL	*- FL
33	1		*FRONT LH AIRBAG SENSOR	Not Damaged	231.11 FL	*- FL
34	1		*RH FRONT SPORT RIM	Cut	1,081.50 FL	*625.00 FL
35	1		*RH FRONT LOWER ARM	Not Damaged	512.50 FL	*- FL
36	1		*RH FRONT SHOCK ABSORBER	Not Damaged	864.90 FL	*- FL
37	1		*RH FRONT KNUCKLE ARM	Dented	1,193.20 FL	*775.00 FL
38	1		*RH FRONT WHEEL BEARING	Jammed	695.00 FL	*285.00 FL
39	1		*RH FRONT CONTROL ARM	Not Damaged	505.00 FL	*- FL
40	1		*BRAKE FLUID	Not Necessary	70.00 FS	*- FS
41	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,329.85	6,991.99
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,017.99	699.20
Total Parts (\$\$)	18,311.86	6,292.79

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGED BODYPARTS.TO PANEL BEATING,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,400.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,300.00	400.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	100.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	0.00
5	REMOVE AND REINSTALL AIRCON CONDENSER AND PIPES.TO REFILL AIRCON GAS	New	220.00	0.00
6	REMOVE AND REINSTALL RADIATOR ASSY,HOSES AND FAN ASSY.TO REFILL COOLANT	New	280.00	0.00
7	REMOVE AND REPLACE FRONT BUMPER SENSOR,RUBBER SEAL AND WIRE HARNESS TO ASSIST REPAIR	New	150.00	60.00
8	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIT REPAIR	New	380.00	150.00
9	ADJUST AND TEST DRIVE WHEEL ALIGNMENT SYSTEM	New	120.00	60.00
Gross Labour Cost (\$)			4,030.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >