

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD		Ref:	CS3/INC22002416/Vvy3e2
	73 BRAS BASAH R UNION HOUSE SIN	ROAD #05-01 NTUC TRADE NGAPORE 189556		Date:	01/04/2022
	ATTN: DAVID PHU	Α		Code:	INC
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XE 2469H	Veh. Inspected		FBR 8160A
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1163082-002	Excess (\$)		0.00
	Assign From	Theresa Vimala	Assign Date		15/03/2022
2. Vehicle Particulars & Condition					
	Make & Model	SUZUKI UH200A	c.c		200
	Engine No.	HIDDEN	Year of Reg.		2020
	Chassis No.	MLCC91327L0407100	Colour		SILVER
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	110/90-13	BRIDGESTONE		5 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	110/90-13	BRIDGESTONE		5 mm
	L/H Rear Tyre				mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S BODY.			
5.	General Information				
	Accident Date	09/02/2022	Inspect Date /	Time	15/03/2022 (04:00 PM)
	Survey held at	GLEN ENTERPRISE PTE LTD			
		1100/1102 SERANGOON ROAD SINGAPORE 328196			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC22002416/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser