

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT NTUC INCOME INSURANCE CO-OPERATIVE LTD CS3/INC22002418/Rvy3e2 Ref: 73 BRAS BASAH ROAD Date: 30/03/2022 #05-01 NTUC TRADE UNION HOUSESINGAPORE ATTN: SERENE LIM INC Code: 1. Policy Particulars :- (THIRD PARTY CLAIM) YN 5536T JRL 2389 Insured Veh. Veh. Inspected 0.00 Policy No. Coverage (\$) MT/1163266-002 0.00 Claim No. Excess (\$) 15/03/2022 Theresa Vimala **Assign Date** Assign From 2. **Vehicle Particulars & Condition** YAMAHA 135 LC Make & Model c.c 134 **HIDDEN Engine No.** Year of Reg. 2016 PMYUG0420G0009338 Chassis No. Colour **RED** Odometer 73771 KM **IN ORDER** Steering **IN ORDER** SPORTS RIM Modification **Brakes** FAIR General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 70/90-17 **MAXXIS** 3 mm L/H Front Tyre mm 80/90-17 **MAXXIS** R/H Rear Tyre 3 mm L/H Rear Tyre mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. 5. **General Information** 25/02/2022 Inspect Date / Time 16/03/2022 (02:31 PM) **Accident Date** Survey held at PROJECT 8 MOTORWORKS 61 WOODLANDS INDUSTRIAL PARK E9, #01-03, E9 PREMIUM, SINGAPORE 757047 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

Report Ref No. CS3/INC22002418/Rvy3e2

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser