



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg Roc/GST: (199806235M)

Vehicle No. YN8778S ISUZU

Page No. 1 - 3

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Front windscreen / BR		850.00	
1	Front windscreen seal / MC		50.00	
1	Front windscreen moulding upper / MC		90.00	
1	Front windscreen moulding lower / MC		100.00	
1	Front panel X R		552.00	
1	Front panel rubber seal X		36.00	
1	Front panel emblem "Isuzu" / MC		108.00	
1	Front panel sticker "Reward-NN" / MC		26.40	
1	Front corner top panel Lh / BR		192.00	
1	Side mirror arm top round cover Lh / MIS		12.00	
1	Center grille whole assy / BR		450.00	
7	Center grille clip @7*\$6 / MC		10 42.00	
1	Front bumper / DD		444.00	
1	Front bumper side bracket Lh / BT		102.00	
1	Headlamp Lh / BR		252.00	
1	Signal lamp Lh / BR		90.00	
1	Condense / DD		528.00	
1	Condense bracket Lh / BT		58.00	
1	Condense bracket rh / BT		58.00	
1	Fan cowling with motor / BR		456.00	
1	Front door lh / DD		816.00	
1	Front Regulator & Motor LH ?		312.00	
1	Front door lower wheel arch garnish lh / CUT		78.00	
1	Front door wheel arch garnish inner rubber seal Lh / CR9		60.00	
1	Front door outer center protector garnish lh / CUT		60.00	
1	Front door lock lh ?		114.00	
1	Front door inner trim board lh / CR9		222.00	
1	Front door window glass lh / BR		280.00	
1	Front door upper hinge lh / BT		82.00	
1	Front door lower hinge lh / BT		82.00	
1	Front door checker lh ?		36.00	
1	Front door signal lamp lh / BR		90.00	
1	Front door weatherstrip lh / CR9		138.00	
1	Step up garnish lh / CR9		114.00	
1	Front door pillar Lh / DD		1,260.00	
1	Front door pillar lower extension Lh / DD		180.00	
1	Pillar Wheel arch rubber seal Lh / CR9		48.00	
1	Pillar inner arch garnish Lh (upper) / CR9		60.00	

1	Door pillar rubber seal Lh	CR4	102.00	
1	Headlamp lower rubber protector Lh	MIS	18.00	
1	Dashboard	CR4	600.00	
1	Floor panel (Repair refer to labour)	XR	-	
			9,248.40	
Part Items Total:			10%	924.84
				10,173.24

Page No. 2 - 3				
SPECIAL NETT ITEMS				
1	ERP sticker	APC	10.00	
1	Front Windscreen Sealant	APC	40	50.00
1	Front Door Pillar sealant LH	APC	20	60.00
1	Headlamp Bulb LH	BR	10	20.00
1	Signal Lamp Bulb LH	BR	10	20.00
1	Front door Signal Lamp LH	BR	10	20.00
1	Front door bulb LH	X		20.00
1	Front Panel sealant	X		80.00
number plate front / BT \$35				
SN Items Total:			280.00	315
Total Parts			10,453.24	

10,488.24



Wah Hong Motors & Credit Pte Ltd
Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)
Email: motor@wahhong.sg
(199806235M)

Vehicle No. YN8778S ISUZU

Page No. 3-3

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	2000.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1400.00	1000
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	90.00	30
4	To remove and replace front Windscreen	150.00	120
5	To remove and refit dashboard and related wire harness and related parts	300.00	200
6	To remove and refit aircon condenser, related pipes and hoses, vaccum and refill aircon gas	100.00	/
7	To remove and refit/replace Front door LH fitting, trimmings, garnish, window glass and lock mechanism	120.00	50
Labour Total :		4160.00	
TOTAL (PARTS & LABOUR):		14613.24	14,648.24

Steve CLKK)
16/3/22, 12.00p

OP- M KL
Ex car-?
L/S
M KL H
10 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: