

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002424/RTY3N2**Date:** 04/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	SNM22D201775
Claimant Vehicle No :	SNC2113M	Insured Vehicle No :	GBJ2282M
Date of Loss:	12/03/2022	Nature of Claim:	TP
		Claim No:	SNM22D201775/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC2113M	Engine No:	3ZRC215426
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Chassis No:	ZSU600137134
Reg. Date:	11/05/2018 (Man. Year: 2018)	Odometer:	57450 km
Colour:	White		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,986.25	2,632.50	2,353.75	47.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	1,250.00	2,500.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,736.25	3,882.50	4,853.75	55.56
Approved Total (Overridden) (\$\$)		3,100.00		
(\$\$)	8,736.25	3,100.00	5,636.25	64.52
+ GST 7.00/7.00% (\$\$)	611.54	217.00	394.54	64.52
Nett Amount (\$\$)	9,347.79	3,317.00	6,030.79	64.52

INSPECTION

Date of Assignment:	15/03/2022	
Date Inspected:	16/03/2022 Inspected At:	Carz Auto Services Pte Ltd - Woodlands (HQ) NO 61, WOODLANDS INDUSTRIAL PARK E9, #04-04 E9 PREMIUM SINGAPORE 757047 Singapore 757047
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Apr 2022)
Parts: M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC2113M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,120.00 FL	*1,120.00 FL
2	1		*TAIL GATE LOGO	Necessary	55.00 FL	*55.00 FL
3	1		*TAIL GATE LAMP LH	Cracked	650.00 FL	*650.00 FL
4	1		*TAIL GATE LAMP RH	Not Necessary	650.00 FL	*- FL
5	1		*TAIL LAMP LH	Cracked	1,400.00 FL	*585.00 FL
6	1		*TAIL LAMP RH	Not Necessary	1,400.00 FL	*- FL
7	1		*REAR BUMPER	Deformed	780.00 FL	*780.00 FL
8	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	35.00 FL	*- FL
9	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	35.00 FL	*- FL
10	1		*REAR BUMPER LOWER COVER	Scratched	280.00 FL	*280.00 FL
11	1		*REAR BUMPER REFLECTOR LH	Not Necessary	55.00 FL	*- FL
12	1		*REAR BUMPER REFLECTOR RH	Not Necessary	55.00 FL	*- FL
13	1		*REAR NUMBER PLATE WITH BRACKET	Not Necessary	50.00 FS	*- FS
14	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,615.00	3,500.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,628.75	867.50
Total Parts (\$\$)	4,986.25	2,632.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND RENEW REAR DAMAGED PARTS;REPLACE REALIGNED ALL AFFECTED PARTS	New	1,400.00	500.00
2	TO RESPRAY AFFECTED AREAS	New	1,600.00	400.00
3	TO REMOVE/REFIX WIRING CHECKS	New	60.00	30.00
4	TO TUFFCOAT AFFECTED AREA	New	120.00	60.00
5	TO REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
6	TO REMOVE/REPLACE REVERSE SENSOR	New	120.00	60.00
7	TO REMOVE AND REPLACE TAIL GATE MECHANISM	New	300.00	80.00
			Gross Labour Cost (\$)	1,250.00
			3,750.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >