5/13/22, 10:33 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CS/CTI22002425/AQY3N2 Our File No:

13/05/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNA00017282203

Claimant Vehicle

SDH2886H

Insured Vehicle GBA7886K No:

No:

Date of Loss:

Reg. Date:

08/03/2022

Nature of Claim: TP

Claim

SNM22D201688/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

SDH2886H Reg No:

MERCEDES-BENZ CLA180, 1.6 COUPE URBAN Make & Model:

(R18 LED) (A)

17/01/2019 (Man. Year: 2018)

Engine No: Chassis No: Odometer:

Yes

27091031791152

60335 km

WDD1173422N739069

Colour:

Engine Capacity: 1595 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 225/40R18 Rear Tyre Size: Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,099.30	3,960.62	2,138.68	35.06
Miscellaneous Items		0.00	0.00	0.00	
Labour		850.00	580.00	270.00	31.76
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,949.30	4,540.62	2,408.68	34.66
	Approved Total (Overridden) (S\$)		3,600.00		
	Nett Amount (S\$)	6,949.30	3,600.00	3,349.30	48.20

INSPECTION

15/03/2022 Date of Assignment:

Jec Autoservice (HQ)

Date Inspected: 23/03/2022 Inspected At: 1 KAKI BUKIT AVE 6 #02-11 AUTOBAY

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: **ADRIAN LING** Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 May 2022)

Parts: 143 MERCEDES-BENZ CLA180 1.6 COUPE URBAN (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SDH2886H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*FRONT BUMPER	Deformed	1,526.90 F	*1,526.90 FL
1		*FRONT BUMPER SIDE HOLDER	N/s Damaged	196.20 F	*98.10 FL
1		*FRONT BUMPER SPONGE	Not Necessary	203.40 F	*- FL
1		*FRONT BUMPER REINFORCEMENT	Not Necessary	585.50 F	*- FL
1		*FRONT GRILLE	Not Necessary	692.10 F	*- FL
1		*FRONT GRILLE CHROME MOULDING LH	Not Necessary	98.40 F	*- FL
1		*HEADLAMP LH	Cracked	2,632.90 F	*2,632.90 FL
1		*FRONT NUMBER PLATE	Dented	30.00 FS	*30.00 FS
1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
1	nort C-CnoN	*FRONT NUMBER PLATE GARNISH	Deformed	53.90 F	*53.90 FL
icilise	part. 3–3pciv	ett. L-Listiteriidisc.	Sub Total (S\$)	6,099.30	4,391.80
- List Item Discount on L Items 0.00/10.00% (S\$)				0.00	431.18
			Total Parts (S\$)	6,099.30	3,960.62
	1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1	1 *FRONT BUMPER 1 *FRONT BUMPER SIDE HOLDER 1 *FRONT BUMPER SPONGE 1 *FRONT BUMPER REINFORCEMENT 1 *FRONT GRILLE 1 *FRONT GRILLE CHROME MOULDING LH 1 *HEADLAMP LH 1 *FRONT NUMBER PLATE 1 *FRONT NUMBER PLATE HOLDER 1 *FRONT BUMPER CLIPS 1 *FRONT NUMBER PLATE GARNISH chise part. S=SpcNett. L=ListItemDisc.	1 *FRONT BUMPER SIDE HOLDER N/s Damaged 1 *FRONT BUMPER SPONGE Not Necessary 1 *FRONT BUMPER REINFORCEMENT Not Necessary 1 *FRONT GRILLE Not Necessary 1 *FRONT GRILLE CHROME MOULDING LH Not Necessary 1 *FRONT GRILLE CHROME MOULDING LH Not Necessary 1 *FRONT GRILLE CHROME MOULDING LH Not Necessary 1 *FRONT NUMBER PLATE Dented 1 *FRONT NUMBER PLATE Dented 1 *FRONT NUMBER PLATE HOLDER Not Necessary 1 *FRONT BUMPER CLIPS Necessary 1 *FRONT NUMBER PLATE GARNISH Deformed chise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 0.00/10.00% (S\$)	1 *FRONT BUMPER Deformed 1,526.90 F 1 *FRONT BUMPER SIDE HOLDER N/s Damaged 196.20 F 1 *FRONT BUMPER SPONGE Not Necessary 203.40 F 1 *FRONT BUMPER REINFORCEMENT Not Necessary 585.50 F 1 *FRONT GRILLE Not Necessary 692.10 F 1 *FRONT GRILLE CHROME MOULDING LH Not Necessary 98.40 F 1 *HEADLAMP LH Cracked 2,632.90 F 1 *FRONT NUMBER PLATE Dented 30.00 FS 1 *FRONT NUMBER PLATE HOLDER Not Necessary 30.00 FS 1 *FRONT BUMPER CLIPS Necessary 50.00 FS 1 *FRONT NUMBER PLATE GARNISH Deformed 53.90 F chise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 6,099.30 - List Item Discount on L Items 0.00/10.00% (S\$) 0.00

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	400.00	300.00
2	SPRAY PAINTING	New	400.00	250.00
3	WIRING	New	50.00	30.00
		Gross Labour Cost (S\$)	850.00	580.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >