

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002426/KTY3N2**Date:** 30/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00252702100		
Claimant Vehicle No :	SLW384D	Insured Vehicle No :	SMW1829U		
Date of Loss:	12/03/2022	Nature of Claim:	TP	Claim No:	SNM22D201732/C02/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW384D	Engine No:	27491030213220
Make & Model:	MERCEDES-BENZ C180, 1.5 (A)	Chassis No:	WDD2050402R008166
Reg. Date:	15/10/2014 (Man. Year: 2014)	Odometer:	117866 km
Colour:	Matt Pink		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45ZR18	Rear Tyre Size:	245/40ZR18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,235.50	7,579.60	24,655.90	76.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,400.00	2,020.00	2,380.00	54.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,635.50	9,599.60	27,035.90	73.80
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	36,635.50	7,500.00	29,135.50	79.53
+ GST 7.00/7.00% (S\$)	2,564.49	525.00	2,039.49	79.53
Nett Amount (S\$)	39,199.99	8,025.00	31,174.99	79.53

INSPECTION

Date of Assignment:	15/03/2022		
Date Inspected:	16/03/2022	Inspected At:	Thiam Heng Huat Pte Ltd (SIN MING) 176 SIN MING DRIVE, #05-14 Singapore 575721
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2022)
Parts:	143	MERCEDES-BENZ C180 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW384D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Bent	2,857.00 FL	*1,909.00 FL
2	1		*FRONT DOOR TOP HINGE O/S	Repair	237.00 FL	*- FL
3	1		*FRONT DOOR LOWER HINGE O/S	Repair	216.00 FL	*- FL
4	1		*FRONT DOOR INNER TRIM BOARD O/S	Serviceable	983.00 FL	*- FL
5	1		*FRONT DOOR OUTER HANDLE O/S	Serviceable	296.00 FL	*- FL
6	1		*FRONT DOOR OUTER HANDLE LOCK SENSOR O/S	Serviceable	195.00 FL	*- FL
7	1		*FRONT DOOR LOCK O/S	Repair	485.00 FL	*- FL
8	1		*FRONT DOOR WINDOW REGULATOR O/S	Serviceable	536.00 FL	*- FL
9	1		*FRONT DOOR WINDOW MOTOR O/S	Serviceable	481.00 FL	*- FL
10	1		*FRONT DOOR WINDOW OUTER CHANNEL O/S	Serviceable	153.00 FL	*- FL
11	1		*FRONT DOOR WINDOW CHROME MOULDING O/S	Serviceable	235.00 FL	*- FL
12	1		*REAR DOOR O/S	Repair	2,595.00 FL	*- FL
13	1		*REAR DOOR TOP HINGE O/S	Repair	275.00 FL	*- FL
14	1		*REAR DOOR LOWER HINGE O/S	Repair	263.00 FL	*- FL
15	1		*REAR DOOR INNER TRIM BOARD O/S	Serviceable	994.00 FL	*- FL
16	1		*REAR DOOR OUTER HANDLE O/S	Serviceable	296.00 FL	*- FL
17	1		*REAR DOOR OUTER HANDLE LOCK SENSOR O/S	Serviceable	195.00 FL	*- FL
18	1		*REAR DOOR LOCK O/S	Repair	385.00 FL	*- FL
19	1		*REAR DOOR WEATHERSTRIP O/S	Serviceable	288.00 FL	*- FL
20	1		*REAR DOOR WINDOW REGULATOR O/S	Serviceable	576.00 FL	*- FL
21	1		*REAR DOOR WINDOW MOTOR O/S	Serviceable	496.00 FL	*- FL
22	1		*REAR DOOR WINDOW OUTER CHANNEL O/S	Serviceable	145.00 FL	*- FL
23	1		*REAR DOOR WINDOW CHROME MOULDING O/S	Serviceable	219.00 FL	*- FL
24	1		*REAR FENDER O/S	Repair	1,629.00 FL	*- FL
25	1		*REAR FENDER COWLING O/S	Serviceable	237.00 FL	*- FL
26	1		*REAR SHOCK ABSORBER O/S	Serviceable	867.00 FL	*- FL
27	1		*REAR SHOCK ABSORBER TOP MOUNT O/S	Serviceable	192.00 FL	*- FL
28	1		*REAR UPPER ARM O/S	Serviceable	644.00 FL	*- FL
29	1		*REAR LOWER ARM O/S	Serviceable	687.00 FL	*- FL
30	1		*REAR STABILIZER ENDLINK O/S	Serviceable	315.00 FL	*- FL
31	1		*REAR WHEEL KNUCKLE O/S	Serviceable	589.00 FL	*- FL
32	1		*REAR WHEEL HUB O/S	Serviceable	312.00 FL	*- FL
33	1		*REAR WHEEL HUB BEARING O/S	Serviceable	276.00 FL	*- FL
34	1		*ROCKER PANEL O/S	Repair	1,784.00 FL	*- FL
35	1		*ROCKER PANEL SKIRTING O/S	Mtg Cracked	818.00 FL	*818.00 FL
36	1		*REAR BUMPER	Repair	1,987.00 FL	*- FL
37	2		*REAR BUMPER SIDE RETAINER	Serviceable	178.00 FL	*- FL
38	1		*FRONT FENDER O/S	Bent	1,229.00 FL	*985.00 FL
39	1		*FRONT FENDER COWLING O/S	Serviceable	215.00 FL	*- FL
40	1		*FRONT SHOCK ABSORBER O/S	Bent	967.00 FL	*697.00 FL
41	1		*FRONT SHOCK ABSORBER TOP MOUNT O/S	Serviceable	212.00 FL	*- FL
42	1		*FRONT UPPER ARM O/S	Serviceable	844.00 FL	*- FL
43	1		*FRONT LOWER ARM O/S	Bent	787.00 FL	*537.00 FL
44	1		*FRONT STABILIZER ENDLINK O/S	Serviceable	315.00 FL	*- FL
45	1		*FRONT WHEEL KNUCKLE O/S	Bent	989.00 FL	*785.00 FL
46	1		*FRONT WHEEL HUB O/S	Bent	312.00 FL	*312.00 FL

Report was unsubmitted during this print-out.

5/30/22, 8:37 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT WHEEL HUB BEARING O/S	Necessary	276.00 FL	*166.00 FL
48	1		*FRONT DOOR WEATHERSTRIP O/S (50%)	Necessary	254.70 FS	*141.50 FS
49	12		*FRONT DOOR INNER TRIM BOARD CLIPS O/S	Not Necessary	66.00 FS	*- FS
50	12		*REAR DOOR INNER TRIM BOARD CLIPS O/S	Not Necessary	66.00 FS	*- FS
51	8		*REAR FENDER COWLING CLIPS O/S	Not Necessary	44.00 FS	*- FS
52	10		*REAR BUMPER CLIPS	Not Necessary	55.00 FS	*- FS
53	1		*ROCKER PANEL SEALANT O/S	Not Necessary	100.00 FS	*- FS
54	8		*FRONT FENDER COWLING CLIPS O/S	Not Necessary	44.00 FS	*- FS
55	1		*VINYL WRAP (PER PANEL) (7 Pcs)	Necessary (5 Pcs only)	2,800.00 FS	*1,250.00 FS
56	1		*REAR ALLOY WHEEL O/S	Serviceable	850.00 FS	*- FS
57	1		*FRONT ALLOY WHEEL O/S	Dented	850.00 FS	*600.00 FS
58	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					35,241.70	8,200.50
- List Item Discount on L Items 10.00/10.00% (\$)					3,006.20	620.90
Total Parts (\$)					32,235.50	7,579.60
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.	New	1,600.00	600.00
2	TO DISCONNECT N/S DOORS WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS OF POWER WINDOWS.	New	100.00	20.00
3	TO REMOVE AND REFIT N/S DOORS COMPONENTS TO REPLACE BOTH N/S DOORS, CHECK ALIGNMENT.	New	200.00	60.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS TO FACILITATE REPAIR.	New	150.00	0.00
5	TO REMOVE AND REPLACE N/S FRONT & REAR TYRE & RIM. TO PERFORM TYRE BALANCING.	New	100.00	20.00
6	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.	New	150.00	60.00
7	TO REMOVE AND REFIT N/S FRONT & REAR UNDERCARRIAGE FOR REPLACEMENT OF PARTS.	New	400.00	200.00
8	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL.	New	1,600.00	1,000.00
9	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR.	New	100.00	60.00
Gross Labour Cost (\$\$)			4,400.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >