LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd Our File No: CS/III22002430/ANY3E2 64 Cecil Street, #04-00 IOB Building

05/08/2022 Date: Singapore 049711

REFERENCE

Insured/Claimant: ComfortDelGro Driving Centre Pte Ltd Policy No: D20MFL0000618_02

10/03/2022 Date of Loss: Nature of Claim: OD Claim No: MFL2022D0001324

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM2784K

Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 2NR5342401

Reg. Date: 25/06/2019 (Man. Year: 2019) Chassis No: MR2B23F3X01178085

Colour: Silver Odometer: 89033 km

Engine Capacity: 1496 cc Market Value/New Car Price: S\$74,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,109.75	1,109.75	0.00	0.00
Miscellaneous Items		120.00	60.00	60.00	50.00
Labour		1,325.00	905.00	420.00	31.70
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	2,554.75	2,074.75	480.00	18.79
	- Excess (S\$)	500.00	500.00	0.00	0.00
	(S\$)	2,054.75	1,574.75	480.00	23.36
	+ GST 7.00/7.00% (S\$)	143.83	110.23	33.60	23.36
	Nett Amount (S\$)	2,198.58	1,684.98	513.60	23.36

INSPECTION

Kang Car Repairers Pte Ltd (HQ) Date of Assignment: 15/03/2022 Present Location:

Kang Car Repairers Pte Ltd (HQ)

No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Date Inspected: 16/03/2022 Inspected At:

Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: **ADRIAN LING** Manager: **HUEY YON**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Aug 2022)

Parts: 143 TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMM2784K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	Bumper, front (WCP)	Deformed	250.00 F	*250.00 F
2	1	Fender RH, front (WCP)	Dented	220.00 F	*220.00 F
3	1	Headlamp RH (WCP)	Cracked	270.00 F	*270.00 F
4	1	*Front bumper retainer, RH (WCP)	Damaged	55.00 F	*55.00 F
5	1	*Front fog lamp cover, RH	Cut	60.00 F	*60.00 F
6	1	*Front fender cowling, RH (WCP)	Deformed	110.00 F	*110.00 F
F=Fra	anchise part.				
			Sub Total (S\$)	965.00	965.00
		+ Margin on L,	N Items 15.00/15.00% (S\$)	144.75	144.75
			Total Parts (S\$)	1,109.75	1,109.75
		Report was unsubmitte	ed during this print-out.		

Recommended Miscellaneous Items

No	Qty	Particulars	Repa	irer's	Amount
Su	<u>oplem</u>	entary #1			
1	1	Front bumper clips (NECESSARY)		60.00	30.00
2	1	Front fender cowling clips RH (NECESSARY)		60.00	30.00
			Sub Total (S\$)	20.00	60.00

Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>			
1 To remove and replace the abovementioned parts. To knock out accident dented portion and cutting welding works.	New	600.00	400.00
2 To spray painting	New	600.00	400.00
3 To check wiring	New	25.00	25.00
4 To check wheel alignment	New	100.00	80.00
Gross L	abour Cost (S\$)	1,325.00	905.00
		10000	

Report was unsubmitted during this print-out.

< END OF ESTIMATES >