

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22002435/EQCN2**Date:** 27/06/2022**REFERENCE**

Insured/Claimant:	LEONG CHEE KIN	Policy No:	1800056754-02	
Date of Loss:	13/03/2022	Nature of Claim:	OD	Claim No: 5723169825SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDJ946X		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK058935
Reg. Date:	21/05/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF43JA147482
Colour:	White	Odometer:	62075 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50ZR17	Rear Tyre Size:	225/50ZR17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,105.00	13,901.68	18,203.32	56.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,574.00	7,244.00	3,330.00	31.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,679.00	21,145.68	21,533.32	50.45
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	41,579.00	20,045.68	21,533.32	51.79
+ GST 7.00/7.00% (S\$)	2,910.53	1,403.20	1,507.33	51.79
Nett Amount (S\$)	44,489.53	21,448.88	23,040.65	51.79

INSPECTION

Date of Assignment:	16/03/2022	
Date Inspected:	15/03/2022	Inspected At: 24 BENOI SECTOR SINGAPORE 629857 REPAIRER: PREMIUM AUTOMOBILES PTE LTD
Estimated Period of Repair:	8.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,379.00 FS	*1,903.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	613.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	254.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE-LH	Not Necessary	72.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	1,478.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	151.00 FS	*- FS
9	1		*FRONT BUMPER GUIDE SECTION-LH	Broken	41.00 FS	*32.24 FS
10	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
11	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
12	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
13	1		*FRONT PARKING AID SENSOR-INNER/OUTER	Not Necessary	265.00 FS	*- FS
14	4		*FRONT PARKING AID SENSOR SEAL RING	Necessary	10.00 FS	*6.64 FS
15	1		*FRONT FENDER-LH	Dented	861.00 FS	*688.80 FS
16	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	211.00 FS	*- FS
17	1		*FRONT FENDER CLOSING ELEMENT-LH	Necessary	81.00 FS	*64.24 FS
18	1		*FRONT FENDER BRACKET-LH	Bent	41.00 FS	*32.72 FS
19	1		*FRONT FENDER BRACE-LH	Bent	132.00 FS	*105.20 FS
20	1		*POP RIVET	Necessary	23.00 FS	*18.24 FS
		6 Pcs				
21	1		*FRONT FENDER BRACKET CENTER-LH	Not Necessary	55.00 FS	*- FS
22	1		*FRONT FENDER BRACKET END-LH	Not Necessary	36.00 FS	*- FS
23	1		*FRONT WHEEL HOUSING LINER-LH	Crushed	260.00 FS	*208.00 FS
24	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
25	1		*FRONT WHEEL SPOILER	Broken	82.00 FS	*65.12 FS
26	1		*FRONT WHEEL SPOILER LOWER-LH	Not Necessary	39.00 FS	*- FS
27	1		*FRONT FENDER STONE CHIP GUARD-LH	Not Necessary	57.00 FS	*- FS
28	1		*FRONT FENDER LEDGE LONG COVER-LH	Crushed	35.00 FS	*27.52 FS
29	1		*FRONT FENDER LEDGE SHORT COVER-LH	Crushed	26.00 FS	*20.16 FS
30	1		*HEADLIGHT-LH	Cut	8,301.00 FS	*6,640.80 FS
31	1		*HEADLIGHT POWER MODULE	Not Necessary	840.00 FS	*- FS
32	1		*HEADLIGHT CONTROL UNIT	Not Necessary	840.00 FS	*- FS
33	1		*HEADLIGHT HOSE-LH	Not Necessary	42.00 FS	*- FS
34	3		*SPACER	Not Necessary	136.00 FS	*- FS
35	1		*LIFT CYLINDER-LH	Not Necessary	231.00 FS	*- FS
36	1		*LIFT CYLINDER BRACKET	Not Necessary	7.00 FS	*- FS
37	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
38	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
39	1		*REFRIGERANT PIPE	Bent	585.00 FS	*468.00 FS
40	1		*REFRIGERANT PIPE BRACKET	Not Necessary	9.00 FS	*- FS
41	1		*SUSPENSION SUBFRAME	Not Necessary	2,096.00 FS	*- FS
42	1		*WISHBONE LINK-LH	Bent	605.00 FS	*483.60 FS
43	1		*WISHBONE SUSPENSION GUIDE-LH	Bent	1,057.00 FS	*845.60 FS
44	1		*WISHBONE GUIDE UPPER-LH	Not Necessary	575.00 FS	*- FS
45	1		*WISHBONE GUIDE-LH	Not Necessary	575.00 FS	*- FS
46	1		*FRONT WHEEL BEARING HOUSING-LH	Bent	1,070.00 FS	*856.00 FS
47	1		*WISHBONE SWIVEL JOINT	Bent	214.00 FS	*170.80 FS
48	1		*WISHBONE WHEEL HUB	Necessary	498.00 FS	*398.00 FS
49	1		*WISHBONE FLANGE DOUBLE BALL BEARING-LH	Necessary	273.00 FS	*218.00 FS
50	1		*SUSPENSION FORKS-LH	Not Necessary	293.00 FS	*- FS
51	2		*COUPLING ROD	Not Necessary	258.00 FS	*- FS
52	1		*ANTI-ROLL BAR	Not Necessary	478.00 FS	*- FS
53	1		*GAS SHOCK ABSORBER	Not Necessary	332.00 FS	*- FS
54	1		*DRIVE SHAFT-LH	Not Necessary	2,999.00 FS	*- FS
55	1		*TRACK ROD	Bent	109.00 FS	*87.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*TIE ROD END	Bent	217.00 FS	*173.60 FS
57	1		*NOISE INSULATION	Not Necessary	640.00 FS	*- FS
58	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
59	1		*LHS FRONT RIM	Repair	0.00 FS	*- FS
			Npa			
60	1		*LHS FRONT TYRE	Torn	320.00 FS	*288.00 FS
			(\$320.00)(90%)			
61	1		*SUNDRIES	Necessary	500.00 FS	*100.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					32,105.00	13,901.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAYING OF LHS FRONT DOOR	New	280.00	280.00
4	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE.TO CARRY OUT VACUUM AND REGAS	New	280.00	280.00
5	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
6	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
7	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER,BONNET AND LHS FRONT DOOR	New	3,500.00	1,650.00
8	TO RENEW LHS FRONT RIM WITH TYRE.TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
9	TO TOW BACK THE VEHICLE FRONT ACCIDENT SCENE	New	280.00	0.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			10,574.00	7,244.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >