

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22002436/EVCE2

Date: 22/07/2022

REFERENCE

Insured/Claimant: SIM JUAT QUEE MICHAEL GABRIEL

Policy No: 1900253629

Date of Loss: 12/03/2022

Nature of Claim: OD

Claim No: 6809334399SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFJ3289R**

Make & Model: AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)

Engine No: CVK087346

Reg. Date: 29/11/2019 (Man. Year: 2019)

Chassis No: WAUZZZF46KA114431

Colour: Blue

Odometer: 26970 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$145,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Continental 5 mm

Rear Left Side: Continental 5 mm

Front Right Side: Continental 5 mm

Rear Right Side: Continental 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	44,835.00	22,340.80	22,494.20	50.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,124.00	8,254.00	7,870.00	48.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	60,959.00	30,594.80	30,364.20	49.81
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	59,859.00	29,494.80	30,364.20	50.73
+ GST 7.00/7.00% (S\$)	4,190.13	2,064.64	2,125.49	50.73
Nett Amount (S\$)	64,049.13	31,559.44	32,489.69	50.73

INSPECTION

Date of Assignment: 16/03/2022

Date Inspected: 15/03/2022 Inspected At:

24 Benoi Sector Singapore 629857

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	2,379.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	254.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	144.00 FS	*- FS
7	1		*RADIATOR GRILLE	Broken	1,478.00 FS	*1,182.40 FS
8	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	302.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	139.00 FS	*110.80 FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	899.00 FS	*719.20 FS
11	2		*FRONT BUMPER REINFORCEMENT BRACKET - LH / RH	Not Necessary	508.00 FS	*- FS
12	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	82.00 FS	*- FS
13	1		*FRONT BUMPER TOP COVER	Broken	143.00 FS	*114.00 FS
14	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
15	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
16	1		*FRONT BUMPER LOCK CARRIER BRACKET	Broken	154.00 FS	*122.80 FS
17	2		*FRONT BUMPER SUPPORT - LH / RH	Necessary	64.00 FS	*51.04 FS
18	4		*POP RIVET	Necessary	4.00 FS	*2.88 FS
19	2		*HORN - LH / RH	Not Necessary	273.00 FS	*- FS
20	2		*HORN SUPPORT - LH / RH	Not Necessary	66.00 FS	*- FS
21	2		*FRONT PARKING AID SENSOR	Not Necessary	530.00 FS	*- FS
22	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
23	1		*SET FRONT BUMPER WIRING	Not Necessary	567.00 FS	*- FS
24	2		*FRONT FENDER - LH / RH	Dented	1,722.00 FS	*1,377.60 FS
25	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	211.00 FS	*- FS
26	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Necessary	162.00 FS	*128.48 FS
27	2		*FRONT FENDER BRACKET - LH / RH	Not Necessary	82.00 FS	*- FS
28	2		*FRONT FENDER BRACKET CLOSING ELEMENT - LH / RH	Not Necessary	110.00 FS	*- FS
29	12		*FRONT FENDER POP RIVET	Necessary	46.00 FS	*36.48 FS
30	2		*FRONT FENDER BRACE - LH / RH	Not Necessary	264.00 FS	*- FS
31	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	522.00 FS	*- FS
32	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	164.00 FS	*- FS
33	2		*FRONT FENDER LEDGE COVER LONG - LH / RH	Necessary	70.00 FS	*55.04 FS
34	2		*FRONT FENDER LEDGE COVER SHORT - LH / RH	Necessary	52.00 FS	*40.32 FS
35	1		*BONNET	Dented	3,425.00 FS	*2,740.00 FS
36	1		*BONNET ATTACHMENT PARTS	Not Necessary	431.00 FS	*- FS
37	2		*BONNET HINGE - LH / RH	Bent	680.00 FS	*543.20 FS
38	3		*BONNET IMPACT PROTECTION - LH / RH / CENTER	Necessary	93.00 FS	*73.20 FS
39	2		*BONNET STRIKER - LH / RH	Not Necessary	112.00 FS	*- FS
40	2		*BONNET LOCK	Not Necessary	455.00 FS	*- FS
41	2		*BONNET ABSORBER	Not Necessary	256.00 FS	*- FS
42	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
43	1		*BONNET BOWDEN CABLE OUTER	Bent	64.00 FS	*50.56 FS
44	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
45	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
46	1		*BONNET LOCK CABLE	Not Necessary	82.00 FS	*- FS
47	1		*BONNET PLENUM CHAMBER	Not Necessary	108.00 FS	*- FS
48	1		*BONNET SOUND ABSORBER	Not Necessary	382.00 FS	*- FS
49	2		*HEADLIGHT - LH / RH	Broken	16,602.00 FS	*12,308.80 FS
50	2		*LIFT CYLINDER - LH / RH	Not Necessary	462.00 FS	*- FS
51	2		*LIFT CYLINDER BRACKET	Not Necessary	14.00 FS	*- FS
52	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
53	1		*LOCK CARRIER	Not Necessary	1,127.00 FS	*- FS
54	2		*LOCK CARRIER BRACKET - LH / RH	Not Necessary	85.00 FS	*- FS
55	1		*A/C CONDENSER	Bent	683.00 FS	*546.00 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
57	1		*CHARGE AIR COOLER	Not Necessary	654.00 FS	*- FS
58	1		*RADIATOR	Not Necessary	1,010.00 FS	*- FS
59	1		*RADIATOR FAN RING	Not Necessary	291.00 FS	*- FS
60	1		*RADIATOR FAN CONTROL UNIT	Not Necessary	2,483.00 FS	*- FS
61	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	64.00 FS	*- FS
62	2		*RADIATOR AIR GUIDE OUTER - LH / RH	Crushed	28.00 FS	*21.76 FS
63	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
64	6		*RADIATOR COOLANT	Not Necessary	282.00 FS	*- FS
65	1		*INTAKE AIR DUCT - RH	Not Necessary	25.00 FS	*- FS
66	1		*INTAKE AIR GUIDE - TOP	Not Necessary	61.00 FS	*- FS
67	1		*INTAKE HOSE	Not Necessary	110.00 FS	*- FS
68	1		*AIR FILTER BOX	Not Necessary	418.00 FS	*- FS
69	1		*AIR MASS METER	Not Necessary	627.00 FS	*- FS
70	2		*FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH	Cut	688.00 FS	*549.60 FS
71	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
72	1		*SUNDRIES	Necessary	400.00 FS	*41.68 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	44,835.00	22,340.80
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS	New	1,400.00	480.00
4	TO DISMANTLE BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAYING OF BOTH FRONT DOOR	New	560.00	560.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION- RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,000.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDER, BOTH FRONT DOORS AND BOTH UPPER A-PILLAR	New	7,000.00	3,850.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			16,124.00	8,254.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >