

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22002438/KQY3N2**Date:** 31/03/2022**REFERENCE**

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326_01

Date of Loss: 09/03/2022

Nature of Claim: OD

Claim No: MFL2022D0001230

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA8457D	Engine No:	L15B5552067
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11302060
Reg. Date:	21/06/2018 (Man. Year: 2018)	Odometer:	74559 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$72,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Davanti 9 mm	Rear Left Side:	Davanti 3 mm
Front Right Side:	Davanti 9 mm	Rear Right Side:	Davanti 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,068.12	4,158.76	3,909.36	48.45
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,670.00	1,300.00	370.00	22.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,749.12	5,469.76	4,279.36	43.89
Approved Total (Overridden) (\$\$)		4,350.00		
- Excess (\$\$)	0.00	750.00	-750.00	
(\$\$)	9,749.12	3,600.00	6,149.12	63.07
+ GST 7.00/7.00% (\$\$)	682.44	252.00	430.44	63.07
Nett Amount (\$\$)	10,431.56	3,852.00	6,579.56	63.07

INSPECTION

Date of Assignment:	15/03/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected:	16/03/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

FOR MANDATE ONLY

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Mar 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA8457D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	745.90 FL	*745.90 FL
2	1		*FRT GRILLE	Cracked	270.20 FL	*270.20 FL
3	1		*FRT GRILLE CHROME	Cracked	227.00 FL	*227.00 FL
4	1		*FRT GRILLE LOGO	Serviceable	27.20 FL	*- FL
5	1		*FRT GRILLE TOP BRACKET (CENTER)	Cracked	42.10 FL	*42.10 FL
6	1		*FRT BUMPER	Buckled	872.20 FL	*762.60 FL
7	1		*FRT BUMPER REINFORCEMENT	Bent	259.20 FL	*259.20 FL
8	1		*FRT BUMPER SIDE RETAINER LH	Distorted	17.10 FL	*17.10 FL
9	1		*FRT BUMPER SIDE RETAINER RH	Serviceable	17.10 FL	*- FL
10	1		*FRT BUMPER LOWER GARNISH	Buckled	196.50 FL	*196.50 FL
11	1		*FRT BUMPER LOWER GRILLE	Cracked	96.40 FL	*96.40 FL
12	10		*FRT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
13	1		*HEADLAMP LH	Mtg Broken	1,793.20 FL	*1,793.20 FL
14	1		*HEADLAMP LOWER BRACKET LH	Cracked	38.90 FL	*38.90 FL
15	1		*HEADLAMP RH	Serviceable	1,793.20 FL	*- FL
16	1		*HEADLAMP LOWER BRACKET RH	Cracked	38.90 FL	*38.90 FL
17	1		*FRT SUPPORT PANEL	Repair	542.20 FL	*- FL
18	1		*FRT SUPPORT PANEL TOP GARNISH	Cracked	56.10 FL	*56.10 FL
19	1		*AIRCON CONDENSOR	Bent	568.10 FL	*568.10 FL
20	1		*AIRCON FAN COWLING	Serviceable	151.50 FL	*- FL
21	1		*AIRCON FAN MOTOR	Serviceable	315.30 FL	*- FL
22	1		*AIRCON FAN BLADE	Serviceable	58.90 FL	*- FL
23	1		*RADIATOR	Serviceable	1,291.70 FL	*- FL
24	1		*RADIATOR FAN COWLING	Serviceable	155.60 FL	*- FL
25	1		*RADIATOR FAN MOTOR	Serviceable	332.80 FL	*- FL
26	1		*RADIATOR FAN BLADE	Serviceable	91.60 FL	*- FL
27	1		*FRT NUMBER PLATE	Bent	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,073.90	5,187.20
- List Item Discount on L Items 20.00/20.00% (S\$)	2,005.78	1,028.44
Total Parts (S\$)	8,068.12	4,158.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS BONNET, FRT BUMPER, FRT SUPPORT PANEL, BOTH HEADLAMP AND ETC	New	720.00	480.00
2	TO PUTTY AND RESRPAY ACCIDENT AREA SUCH AS BONNET, FRT BUMPER, FRT SUPPORT PANEL AND ETC	New	800.00	700.00
3	TO CHECK WIRING AND LIGHTING	New	50.00	20.00
4	TO DISCHAGE AND CHARGE AIRCON GAS	New	100.00	100.00
Gross Labour Cost (\$\$)			1,670.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >