

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22002440/UEA3Q2**Date:** 13/07/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070123410
<b>Claimant Vehicle No :</b>	SMP2761K	<b>Insured Vehicle No :</b>	GBF2789P
Date of Loss:	15/03/2022	Nature of Claim:	TP
		Claim No:	2390543489SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMP2761K</b>	Engine No:	LEB5618717
Make & Model:	HONDA FREED, 1.5 G (A)	Chassis No:	GB71081974
Reg. Date:	19/09/2019 (Man. Year: 2018)	Odometer:	198435 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Winrun 7 mm	Rear Left Side:	Winrun 7 mm
Front Right Side:	Winrun 7 mm	Rear Right Side:	Winrun 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,892.92	2,091.28	7,801.64	78.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,520.00	1,680.00	2,840.00	62.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,412.92</b>	<b>3,771.28</b>	<b>10,641.64</b>	<b>73.83</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,412.92</b>	<b>3,000.00</b>	<b>11,412.92</b>	<b>79.19</b>
<b>+ Car Rental (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>+ Other Costs (S\$)</b>		20.00		
<b>Nett Liability (S\$)</b>		<b>3,622.00</b>		

**INSPECTION**

Date of Assignment:	16/03/2022	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Date Inspected:	16/03/2022		
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN GLASS	Shattered	1,055.00 FL	*1,055.00 FL
2	1		*REAR TAILGATE	Repair	1,460.70 FL	*- FL
3	1		*REAR TAILGATE DAMPER	Not Necessary	90.70 FL	*- FL
4	1		*REAR TAILGATE INNER BOARD	Not Necessary	391.70 FL	*- FL
5	1		*REAR TAILGATE LAMP -RH	Serviceable	322.00 FL	*- FL
6	1		*REAR TAILGATE LOCK	Not Necessary	186.20 FL	*- FL
7	1		*REAR TAILGATE LOGO	Necessary	90.70 FL	*38.50 FL
8	1		*REAR TAILGATE RUBBER	Not Necessary	188.70 FL	*- FL
9	1		*REAR TAILGATE FREED EMBLEM	Necessary	100.30 FL	*58.00 FL
10	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	83.00 FL	*60.00 FL
11	1		*REAR TAILLAMP -RH	Cracked	458.70 FL	*458.70 FL
12	1		*REAR END PANEL	Not Necessary	520.30 FL	*- FL
13	1		*REAR END PANEL INNER GARNISH	Not Necessary	199.70 FL	*- FL
14	1		*REAR BUMPER	Deformed / Torn	967.30 FL	*698.50 FL
15	1		*REAR BUMPER BEAM	Not Necessary	288.70 FL	*- FL
16	1		*REAR BUMPER REFLECTOR (O/S )	Cracked	42.00 FL	*42.00 FL
17	1		*REAR BUMPER SIDE RETAINERS	O/S Cracked	81.80 FL	*40.90 FL
18	1		*REAR FENDER RH	Repair	1,294.60 FL	*- FL
19	1		*REAR FENDER QUARTER GLASS MOULDING	Not Necessary	115.00 FL	*- FL
20	1		*REAR WHEEL HUB WITH BEARING	Not Necessary	321.40 FL	*- FL
21	1		*REAR SHOCK ABSORBER	Not Necessary	336.40 FL	*- FL
22	1		*REAR AXLE BEAM	Not Necessary	1,085.00 FL	*- FL
23	1		*REAR KNUCKLE ARM	Not Necessary	355.00 FL	*- FL
24	1		*REAR WINDSCREEN INNER SEAL	Necessary	85.00 FS	*40.00 FS
25	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
26	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
27	1		*SET REAR REVERSE SENSOR	Not Necessary	350.00 FS	*- FS
28	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	50.00 FS	*- FS
29	1		*REAR TYRE	Not Necessary	400.00 FS	*- FS
30	1		*REAR WHEEL RIM -RH	Not Necessary	850.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,899.90</b>	<b>2,581.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	2,006.98	490.32
<b>Total Parts (\$\$)</b>	<b>9,892.92</b>	<b>2,091.28</b>

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REPLACE DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	0.00
5	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	280.00	0.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	0.00
7	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
8	TO REMOVE AND REFIT QUARTER GLASS TO ASSIST REPAIR	New	120.00	0.00
9	TO APPLY UNDERCOATING	New	200.00	30.00
10	PANEL BEATING	New	1,600.00	580.00
11	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,520.00</b>	<b>1,680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >