



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 7753S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,800.00	1,280.00
1	FRONT BUMPER SIDE RETAINER LH	NOT NECESSARY	60.00	-
1	FRONT BUMPER CHROME LH	CUT	150.00	150.00
1	FRONT BUMPER PROTECTOR LH	DEFORMED	265.00	265.00
1	HEADLAMP LH	CUT	3,100.00	1,355.00
1	FOG LAMP GARNISH LH	CRACKED	145.00	145.00
1	FOG LAMP LH	NOT NECESSARY	450.00	-
1	FOG LAMP CHROME LH	CUT	72.00	72.00
	LESS 20% DISCOUNT		-604.20	-326.70
			5,437.80	2,940.30
	<u>SPECIAL NETT ITEMS</u>			
10	FRONT BUMPER CLIP @\$9.00 (SN)	NECESSARY	90.00	30.00
			90.00	30.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND REFOCUS HEADLAMP LH.		60.00	30.00
	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS.		400.00	250.00
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.		500.00	250.00
	ANTI-RUST UNDERCOATING.	NOT NECESSARY	30.00	-
			990.00	530.00
	GRAND TOTAL		6,517.80	3,500.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00

Report Ref No. CS/AIS22002445/Aty3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.