

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002446/KVY3N2**Date:** 05/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00065362101		
Claimant Vehicle No :	SMT6130J	Insured Vehicle No :	GBD8657H		
Date of Loss:	14/03/2022	Nature of Claim:	TP	Claim No:	SNM22D201792/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT6130J		Engine No:	LEB5624034
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)		Chassis No:	GB71086272
Reg. Date:	26/07/2019 (Man. Year: 2018)		Odometer:	86527 km
Colour:	Metallic Grey			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Firenza 9 mm	Rear Left Side:	Firenza 7 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Firenza 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,391.40	5,001.44	3,389.96	40.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,660.00	2,260.00	3,400.00	60.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	14,051.40	7,261.44	6,789.96	48.32

INSPECTION

Date of Assignment:	16/03/2022	
Date Inspected:	16/03/2022 Inspected At:	Guan Hin Motor Workshop (HQ) BLK 10 ANG MO KIO IND PARK 2A #02-03 AMK AUTOPOINT Singapore 568047
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2022)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT6130J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	897.00 F	*841.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Repair	373.40 F	*- FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	16.00 F	*16.00 FL
4	1		*GRILL	Serviceable	836.90 F	*- FL
5	1		*LH HEAD LAMP	Cut	1,453.30 F	*1,453.30 FL
6	1		*FRONT LH FENDER	Bent	473.60 F	*473.60 FL
7	1		*HYBRID EMBLEM	Necessary	85.10 F	*85.10 FL
8	1		*FRONT LH DOOR	Bent	947.10 F	*947.10 FL
9	1		*FRONT LH DOOR HINGE TOP	Repair	48.50 F	*- FL
10	1		*FRONT LH DOOR HINGE LOWER	Bent	48.50 F	*48.50 FL
11	1		*WIPER GARNISH SIDE COVER	Serviceable	60.50 F	*- FL
12	1		*LH SIDE MIRROR	Dented/Cut	779.30 F	*779.30 FL
13	1		*LH SIDE MIRROR COVER	Dented/Cut	75.40 F	*75.40 FL
14	1		*FRONT LH KNUCKLE ARM	Bent	283.70 F	*283.70 FL
15	1		*FRONT LH KNUCKLE ARM BEARING	Necessary	161.00 F	*161.00 FL
16	1		*FRONT LH SHOCK ABSORBER	Bent	360.30 F	*360.30 FL
17	1		*FRONT LH LOWER ARM	Distorted	285.00 F	*285.00 FL
18	1		*FRONT LH FENDER INNER SHIELD	Cracked	130.00 F	*130.00 FL
19	1		*LH DOOR PILLAR	Repair	826.80 F	*- FL
20	1		*SPORT RIM	Dented	250.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,391.40	6,189.30
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,187.86
Total Parts (\$)	8,391.40	5,001.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUTTING & WELDING LH DOOR PILLAR.JACK OUT FLOOR PANEL.REPLACEMENT OF DAMAGED PARTS ETC	New	2,500.00	800.00
2	REMOVE & FIX BACK TRIANGLE GLASS	New	100.00	0.00
3	REMOVE & FIX BACK UNDERCARRIAGE	New	280.00	180.00
4	TRANSFER FRT LH DOOR MECHANISM	New	100.00	60.00
5	WHEEL ALIGNMENT	New	80.00	60.00
6	ANTI-RUST	New	350.00	60.00
7	SPRAY PAINTING	New	1,800.00	1,100.00
8	REMOVE & FIX BACK DASHBOARD	New	350.00	0.00
9	REMOVE & FIX BACK CARPET AND SHAMPO	New	100.00	0.00
Gross Labour Cost (\$\$)			5,660.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >