

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002449/VNY3M4**Date:** 01/09/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00006792200

Claimant Vehicle No : SMM1126S**Insured Vehicle No :** GBL3177S

Date of Loss: 15/03/2022

Nature of Claim: TP

Claim No: SNM22D201798/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMM1126S**Make & Model: MERCEDES-BENZ E300, 2.0 EXCLUSIVE (18 LED)
(A)

Engine No: 26492030122524

Reg. Date: 18/06/2019 (Man. Year: 2019)

Chassis No: WDD2130832A648387

Colour: Black

Odometer: 12784 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Rear Tyre Size: 245/45 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,691.10	2,800.20	8,890.90	76.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,230.00	490.00	3,740.00	88.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,921.10	3,290.20	12,630.90	79.33
Approved Total (Overridden) (S\$)		2,650.00		
Nett Amount (S\$)	15,921.10	2,650.00	13,271.10	83.36

INSPECTION

Date of Assignment: 21/03/2022

Date Inspected: 17/03/2022 Inspected At:

8 KAKI BUKIT AVENUE 4

#01-49 PREMIER @ KAKI BUKIT

REPAIRER: J.E.W AUTO PTE LTD

Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Sep 2022)

Parts: 143 MERCEDES-BENZ E300 2.0 EXCLUSIVE (18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMM1126S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	2,158.00 FL	*1,680.00 FL
2	1		*REAR BUMPER LH SIDE CHROME MOULDING	Distorted	241.00 FL	*241.00 FL
3	1		*REAR BUMPER RH SIDE CHROME MOULDING	Serviceable	241.00 FL	*- FL
4	1		*REAR BUMPER LH REFLECTOR	Cracked	46.00 FL	*46.00 FL
5	1		*REAR BUMPER LOWER GARNISH	Cut	582.00 FL	*480.00 FL
6	1		*REAR BUMPER LOWER GARNISH CHROME MOULDING	Cut	201.00 FL	*201.00 FL
7	1		*REAR BUMPER LH EXHAUST CHROME FINISHER	Serviceable	142.00 FL	*- FL
8	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Cut	198.00 FL	*150.00 FL
9	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Serviceable	198.00 FL	*- FL
10	1		*REAR BUMPER REVERSE SENSOR RUBBER SEAL (6PCS)	Necessary	74.00 FL	*74.00 FL
11	6		*REAR BUMPER REVERSE SENSOR HOLDERS	Necessary	108.00 FL	*108.00 FL
12	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Serviceable	189.00 FL	*- FL
13	1		*REAR BUMPER LH SIDE RETAINER	Necessary	98.00 FL	*98.00 FL
14	1		*REAR BUMPER RH SIDE RETAINER	Serviceable	98.00 FL	*- FL
15	1		*REAR BUMPER CENTRE BRACKET	Serviceable	108.00 FL	*- FL
16	1		*REAR BUMPER LOWER BRACKET	Serviceable	82.00 FL	*- FL
17	1		*REAR BUMPER KEYLESS SENSOR	Serviceable	151.00 FL	*- FL
18	1		*REAR BUMPER KEYLESS SENSOR CONTROL UNIT	Serviceable	188.00 FL	*- FL
19	1		*REAR BUMPER KEYLESS SENSOR UPPER	Serviceable	166.00 FL	*- FL
20	1		*REAR BUMPER REINFORCEMENT	Serviceable	502.00 FL	*- FL
21	1		*LH TAILLAMP ASSY	Serviceable	872.00 FL	*- FL
22	1		*LH TAILLAMP LOWER BRACKET	Serviceable	89.00 FL	*- FL
23	1		*EXHAUST SILENCER	Serviceable	1,904.00 FL	*- FL
24	1		*EXHAUST SILENCER GASKET	Serviceable	83.00 FL	*- FL
25	1		*REAR WINDSCREEN GLASS WITH RUBBER MOULDING	Serviceable	1,643.00 FL	*- FL
26	1		*LH REAR FENDER	Serviceable	2,317.00 FL	*- FL
27	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
28	1		*SET REAR BUMPER RIVETS	Not Necessary	70.00 FS	*- FS
29	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	80.00 FS	*- FS
30	1		*REAR WINDSCREEN GLASS SPONGE SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,959.00	3,108.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,267.90	307.80
Total Parts (\$\$)	11,691.10	2,800.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AND CONSISTENT AREAS	New	1,200.00	200.00
2	SPRAY PAINT ON AFFECTED AND CONSISTENT AREAS	New	1,000.00	200.00
3	TO CHECK ALL WIRING AND ALL LIGHTING SYSTEM	New	100.00	30.00
4	TO RUST PROOFING ON AFFECTED AND CONSISTENT AREAS	New	80.00	30.00
5	TO REMOVE AND REFIX REAR WINDSCREEN GLASS	New	250.00	0.00
6	TO REMOVE AND REFIX ROOF LINING, SEATS AND CARPET TO CARRY OUT REPAIR	New	500.00	0.00
7	TO REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS	New	180.00	30.00
8	TO REMOVE AND REPLACE EXHAUST SILENCER	New	320.00	0.00
9	TO REMOVE AND REPLACE REAR TRIMS AND BOARDS TO CARRY REPAIR	New	250.00	0.00
10	TO RESET FAULT CODE FROM CONTROL UNIT	New	350.00	0.00
Gross Labour Cost (S\$)			4,230.00	490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >