



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 9653U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR - RH	BENT / WARPED	2,884.00	2,201.00
1	FRONT DOOR LOCK	NOT NECESSARY	418.00	-
1	FRONT DOOR "RENEGADE" EMBLEM	NECESSARY	115.00	115.00
1	FRONT DOOR RUBBER	NOT NECESSARY	334.00	-
1	FRONT DOOR OUTER LOWER GARNISH	GRAZED	517.00	502.00
1	REAR DOOR - RH	TO REPAIR SEE LABOUR	3,080.00	-
1	REAR DOOR RUBBER	NOT NECESSARY	334.40	-
1	REAR DOOR OUTER LOWER GARNISH	NOT NECESSARY	517.00	-
1	FRONT FENDER - RH	DENTED / BENT	895.00	895.00
1	FRONT FENDER WHEEL ARCH GARNISH	TORN	495.00	495.00
1	FRONT WHEEL HUB	WARPED	525.00	525.00
1	FRONT WHEEL BEARING	DAMAGED	415.00	380.00
1	FRONT SHOCK ABSORBER	NOT NECESSARY	700.00	-
1	FRONT LOWER ARM	NOT NECESSARY	1,075.00	-
1	STABILIZER BAR LINK	NOT NECESSARY	130.00	-
1	FRONT DRIVE SHAFT	NOT NECESSARY	2,750.00	-
1	FRONT KNUCKLE ARM	WARPED	1,525.00	980.00
	LESS 10% DISCOUNT		-1,670.94	-609.30
			15,038.46	5,483.70
1	FRONT WHEEL RIM - RH (SN)	WARPED	3,875.00	600.00
	LESS 10% DISCOUNT		-387.50	-
			3,487.50	600.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE (SN)	SERVICEABLE	600.00	-
			600.00	-
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.		80.00	20.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		400.00	120.00

Report Ref No. CS/AGI22002451/Uty3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT WHEEL ALIGNMENT.		180.00	100.00
	TO REMOVE, REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.		400.00	80.00
	TO APPLY UNDERCOATING.		200.00	60.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR DOOR - RH.		1,500.00	400.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,400.00	700.00
			4,160.00	1,480.00
GRAND TOTAL			23,285.96	7,563.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,000.00

Report Ref No. CS/AGI22002451/Uty3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.