

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22002452/GVY3E2

Date: 05/04/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00111862103
Claimant Vehicle No : SBS6001J **Insured Vehicle No :** YN9175A
Date of Loss: 10/03/2022 Nature of Claim: TP Claim No: SNM22D201710/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS6001J**
Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D (A) Engine No: 90292609015179
Reg. Date: 26/04/2011 (Man. Year: 2011) Chassis No: WEB62808323121888
Colour: Multi-colour Odometer: 687313 km
Engine Capacity: 6374 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5(D)
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	917.00	917.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	660.00	660.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,577.00	1,577.00	0.00	0.00
+ GST 7.00/7.00% (\$\$)	110.39	110.39	0.00	0.00
Nett Amount (\$\$)	1,687.39	1,687.39	0.00	0.00

INSPECTION

Date of Assignment: 20/03/2022
Date Inspected: 16/03/2022 Inspected At: Sbs Transit Ltd (Bedok) (HQ)
1470 BEDOK NORTH AVE 4
Singapore 489946
Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Apr 2022)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS6001J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH TAILLAMP	Cracked	467.00 F	*467.00 F
2	1		*CCTV DOME	Cracked	450.00 F	*450.00 F
3	1		*ENGINE PANEL (NPA)	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					917.00	917.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CONTRACTOR LABOUR COST	New	660.00	660.00
Gross Labour Cost (\$\$)			660.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >