



Accident Reference & Bus No: **E/1138/2022 – SBS6001J with YN9175A**

Activated date: **16/03/2022**

Activated by: Yao Tianhao <yaoth@sbstransit.com.sg>

Name of Surveyor: Guo Qiang

Company Name: LKK

Date Surveyed: 16/3/22

Require

Resurvey 1 Date:

Resurvey 2 Date:

82880282
GuoQiang@lkkauto.com
After npi photos

Replace

- Rear ~~LH~~ Tailamp — CRA 467

- Cctr dome — CRA 450

Repair

- engine panel x npi

Respray paint

- engine panel

Final Endorsement by Surveyor:

Estimate for

- * ☒ Parts cost: \$ 917
- * ☒ Contractor Labour cost: \$ 660
- * ☒ Workshop Labour cost: \$
- * ☒ Advertisement Cost: \$
- * ☒ Repair period: 2 day

Total: 1577

- / ☐ Tow Cost: \$ 0
- * ☐ Loss of use: \$
- * ☐ Overheads: \$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: