



Accident Reference & Bus No: **E/1138/2022 – SBS6001J with YN9175A**

Activated date: **16/03/2022**

Activated by: Yao Tianhao <yaoth@sbstransit.com.sg>

Name of Surveyor: Guo Qiang
 Company Name: LKK
 Date Surveyed: 16/3/22
82880282
 Require GuoQiang@lkkauto
 Resurvey 1 Date: After npi photos
 Resurvey 2 Date: com

Replace
 - Rear ~~LH~~ Tailamp — CRA
 - Cctr dome — CRA
 Repair
 - engine panel x npi
 Respray paint
 - engine panel

Final Endorsement by Surveyor:

Estimate for

- * ☒ Parts cost: \$ _____
- * ☒ Contractor Labour cost: \$ _____
- * ☒ Workshop Labour cost: \$ _____
- * ☒ Advertisement Cost: \$ _____
- * ☒ Repair period: 2 day

- / ☐ Tow Cost: \$ 0
- * ☐ Loss of use: \$ _____
- * ☐ Overheads: \$ _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: