

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002455/UTY3N2**Date:** 24/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00005342100
Claimant Vehicle No :	SJK3753P	Insured Vehicle No :	SNA1421R
Date of Loss:	14/03/2022	Nature of Claim:	TP
		Claim No:	SNM22D201807/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK3753P	Engine No:	1ZZ3092036
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100407443
Reg. Date:	16/10/2008 (Man. Year: 2008)	Odometer:	190494 km
Colour:	Black		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,760.07	1,877.57	882.50	31.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,880.00	340.00	15.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,980.07	3,757.57	1,222.50	24.55
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	4,980.07	3,000.00	1,980.07	39.76
+ GST 7.00/7.00% (S\$)	348.60	210.00	138.60	39.76
Nett Amount (S\$)	5,328.67	3,210.00	2,118.67	39.76

INSPECTION

Date of Assignment:	16/03/2022	
Date Inspected:	28/03/2022	Inspected At: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK3753P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	500.00 FL	*500.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
3	1		*REAR BUMPER SIDE HOLDER-RH	Not Necessary	70.00 FL	*- FL
4	1		*REAR BUMPER SIDE HOLDER-LH	Bent	70.00 FL	*70.00 FL
5	1		*REAR BUMPER REFLECTORS-LH	Broken	60.00 FL	*60.00 FL
6	1		*REAR BUMPER BRACKETS-LH	Bent	85.00 FL	*85.00 FL
7	1		*REAR FENDER-LH	Badly Dented	950.00 FL	*950.00 FL
8	1		*REAR FENDER GLASS MOULDING-LH	Not Necessary	500.00 FL	*- FL
9	1		*TAIL LAMP-LH	Broken	497.00 FL	*497.00 FL
10	1		*REAR MUDFLAP LH	Torn	98.10 FL	*98.10 FL
11	1		*SET REAR NUMBER PLATE WITH CASING	Not Necessary	35.00 FS	*- FS
12	2		*END PANEL SEALANT	Necessary	40.00 FS	*40.00 FS
13	1		*SPONGE TAPE	Not Necessary	20.00 FS	*- FS
14	1		*SET REAR BUMPER SENSOR (4PCS)	Not Necessary	400.00 FS	*- FS
15	1		*REAR FENDER INNER AIR GUIDE-LH	Cracked	140.00 FL	*140.00 FL
					Sub Total (\$\$)	3,515.10 2,490.10
					- List Item Discount on L Items 25.00/25.00% (\$\$)	755.03 612.53
					Total Parts (\$\$)	2,760.07 1,877.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS,CUT/WELD REAR PANEL,REMOVE,REPLACE ACCIDENT PARTS	New	1,000.00	900.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,000.00	800.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE,REFIT REAR LH FENDER BOOT GLASS	New	60.00	60.00
5	TO TUFF-KOTE	New	60.00	50.00
6	TO TRANSFER REAR BUMPER SENSOR	New	50.00	50.00
Gross Labour Cost (\$\$)			2,220.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >