

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 9529H

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|--------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER (CONSISTENT) | DEFORMED | 1,112.00 | 1,112.00 |
| 1 | REAR BUMPER SIDE HOLDER LH (CONSISTENT) | DAMAGED | 44.00 | 44.00 |
| 1 | REAR BUMPER REFLECTOR LH (CONSISTENT) | CUT | 78.00 | 78.00 |
| 1 | REAR BUMPER REINFORCEMENT (CONSISTENT) | DENTED | 545.00 | 545.00 |
| 1 | REAR BUMPER CENTRE GUIDE (CONSISTENT) | CRACKED | 195.00 | 195.00 |
| 1 | REAR BUMPER LOWER GARNISH (CONSISTENT) | CUT | 325.00 | 325.00 |
| 1 | REAR BUMPER LOWER GARNISH CHROME MOULDING (CONSISTENT) | NECESSARY | 145.00 | 145.00 |
| 2 | REVERSE SENSOR @\$228.00 (CONSISTENT) | DAMAGED (1PIECE ONLY) | 456.00 | 228.00 |
| 4 | REVERSE SENSOR HOLDER @\$25.00 (CONSISTENT) | NECESSARY | 100.00 | 100.00 |
| 1 | REAR END PANEL (CONSISTENT) | DENTED | 753.00 | 753.00 |
| 1 | REAR END PANEL TOP GARNISH (CONSISTENT) | NOT NECESSARY | 167.00 | - |
| 1 | TAILLAMP LH (CONSISTENT) | CRACKED | 368.00 | 368.00 |
| 1 | TAILLAMP PANEL LH (CONSISTENT) | TO REPAIR SEE LABOUR | 308.00 | - |
| 1 | TAILGATE (CONSISTENT) | DENTED | 1,634.00 | 1,634.00 |
| 1 | TAILGATE LOCK (CONSISTENT) | NOT NECESSARY | 198.00 | - |
| 1 | TAILGATE WEATHERSTRIP (CONSISTENT) | CUT | 225.00 | 225.00 |
| 1 | TAILGATE REFLECTOR LH (CONSISTENT) | CUT | 342.00 | 342.00 |
| 1 | TAILGATE INNER TRIM BOARD (CONSISTENT) | DEFORMED | 305.00 | 305.00 |
| 1 | TAILGATE GLASS (CONSISTENT) | SHATTERED | 1,124.00 | 1,124.00 |
| 1 | TAILGATE GLASS MOULDING (CONSISTENT) | NECESSARY | 184.00 | 184.00 |
| 1 | VOLKSWAGEN LOGO (CONSISTENT) | NECESSARY | 130.00 | 130.00 |
| 1 | GOLF WORDING (CONSISTENT) | NECESSARY | 88.00 | 88.00 |
| 1 | REAR LH FENDER (CONSISTENT) | DISTORTED | 985.00 | 985.00 |
| 1 | REAR LH FENDER AIR VENT (CONSISTENT) | DEFORMED | 48.00 | 48.00 |
| 1 | REAR LH FENDER INNER SHIELD (CONSISTENT) | TORN | 185.00 | 185.00 |
| 1 | REAR LH FENDER INNER TRIM (CONSISTENT) | NOT NECESSARY | 395.00 | - |
| 1 | REAR LH FENDER INNER TRIM COVER UPPER (CONSISTENT) | CRACKED | 325.00 | 325.00 |
| 1 | REAR LH WHEEL RIM (CONSISTENT) | NOT NECESSARY | 1,048.00 | - |

Report Ref No. CS/ASM22002459/Avy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|-------------------------------|-------------------|
| | LESS 10% DISCOUNT | | - | -946.80 |
| | | | 11,812.00 | 8,521.20 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REAR BUMPER CLIPS (SN) (CONSISTENT) | NECESSARY | 30.00 | 30.00 |
| 1 | REAR END PANEL SEALANT (SN) (CONSISTENT) | NECESSARY | 60.00 | 60.00 |
| 1 | TAILGATE INNER TRIM BOARD CLIPS (SN) (CONSISTENT) | NECESSARY | 30.00 | 30.00 |
| 1 | TAILGATE GLASS SEALANT (SN) (CONSISTENT) | NECESSARY | 60.00 | 60.00 |
| 1 | TAILGATE GLASS SOLAR FILM (SN) (CONSISTENT) | NECESSARY | 280.00 | 200.00 |
| 1 | REAR LH FENDER INNER SHIELD CLIPS (SN) (CONSISTENT) | NECESSARY | 30.00 | 30.00 |
| 1 | REAR LH FENDER INNER TRIM CLIPS (SN) (CONSISTENT) | NOT NECESSARY | 30.00 | - |
| 1 | REAR LH FENDER INNER TRIM COVER UPPER CLIPS (SN) (CONSISTENT) | NECESSARY | 20.00 | 20.00 |
| 1 | REAR LH TYRE (SN) (CONSISTENT) | NOT NECESSARY | 250.00 | - |
| | | | 790.00 | 430.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL LH. | | 1,400.00 | 1,200.00 |
| | SPRAY PAINTING. | | 1,400.00 | 1,000.00 |
| | WIRING. | | 50.00 | 30.00 |
| | TO REMOVE REVERSE SENSOR. | | 100.00 | 50.00 |
| | TO REMOVE REAR CAMERA. | | 100.00 | 50.00 |
| | TO REMOVE UPHOLSTERY. | | 150.00 | 60.00 |
| | TO TRANSFER TAILGATE FITTINGS. | | 150.00 | 60.00 |
| | TO REMOVE TAILGATE GLASS. | | 180.00 | 120.00 |
| | TO VACCUM AND CLEAN UP GLASS FRAGMENTS. | | 120.00 | 60.00 |
| | TO SPRAY TUFF COAT. | | 150.00 | 60.00 |
| | | | 3,800.00 | 2,690.00 |
| | GRAND TOTAL | | 16,402.00 | 11,641.20 |



Page No.:3 of 3

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 9,300.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | |

Report Ref No. CS/ASM22002459/Avy3m4



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.