

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 8927C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,655.00	-
1	REAR BUMPER BRACKET	NECESSARY	188.00	90.00
1	REAR BUMPER REFLECTOR RIGHT	DAMAGED	396.00	136.00
1	REAR REINFORCEMENT BAR	SERVICEABLE	789.00	-
1	REAR END PANEL	SERVICEABLE	755.00	-
1	REAR FENDER	DAMAGED	998.00	798.40
1	REAR RIGHT TAIL LAMP	BROKEN	858.00	598.60
1	REAR RIGHT BOOT LAMP	SERVICEABLE	669.00	-
	LESS 20% DISCOUNT		-1,261.60	-324.60
			5,046.40	1,298.40
	<u>LABOUR</u>			
	TO FIX & DISMANTLE & REMOVE DAMAGED REAR PORTION; AFFECTED DAMAGED PORTION. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		1,000.00	600.00
	TO APPLY ANTI RUST COAT AFFECTED AREAS. }		180.00	50.00
	TO APPLY WATERPROOFING SEALER ON END PANELS.		120.00	-
	TO CHECK WIRING.		120.00	30.00
	WELDING AND CUTTING OF AFFECTED PANELS INCLUDING CHASSIS ALIGNMENT.	NOT NECESSARY	800.00	-
	SPRAY PAINTING FOR REAR PORTIONS AFFECTED PARTS.		800.00	600.00
	REFOCUSING OF THE FRONT HEADLAMP. (NPA)	NOT NECESSARY	-	-
	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE. (NPA)	NOT NECESSARY	-	-
	3D WHEEL ALIGNMENT. (NPA)	NOT NECESSARY	-	-
			3,020.00	1,280.00
	GRAND TOTAL		8,066.40	2,578.40



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,050.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS1/SMR22002465/Vqy3e2



THEVAN THOMAS KARTHIKESAVAN



**ANG BRYAN TANI** 

**Automotive Assessor / Investigator**