

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22002466/DQY3E2**Date:** 27/09/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001898441
Claimant Vehicle No :	SJR4067T	Insured Vehicle No :	SMV7885Y
Date of Loss:	15/03/2022	Nature of Claim:	TP
		Claim No:	271316

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR4067T	Engine No:	L13A4173097
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61158298
Reg. Date:	23/06/2009 (Man. Year: 2009)	Odometer:	182145 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R14	Rear Tyre Size:	185/60 R14
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,389.44	3,002.24	11,387.20	79.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,250.00	1,630.00	4,620.00	73.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,639.44	4,632.24	16,007.20	77.56
Approved Total (Overridden) (\$\$)		3,700.00		
(\$\$)	20,639.44	3,700.00	16,939.44	82.07
+ GST 7.00/7.00% (\$\$)	1,444.76	259.00	1,185.76	82.07
Nett Amount (\$\$)	22,084.20	3,959.00	18,125.20	82.07

INSPECTION

Date of Assignment:	16/03/2022	
Date Inspected:	17/03/2022 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2022)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR4067T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,414.00 FL	*796.00 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	195.60 FL	*74.00 FL
3	1		*TAILGATE WIPER MOTOR	Not Necessary	325.00 FL	*- FL
4	1		*TAILGATE WIPER BLADE	Not Necessary	98.60 FL	*- FL
5	1		*TAILGATE CENTER GARNISH	Not Necessary	369.80 FL	*- FL
6	1		*TAILGATE HONDA LOGO	Not Necessary	55.70 FL	*- FL
7	2		*TAILGATE NO. PLATE LAMP LH / RH	Not Necessary	197.00 FL	*- FL
8	1		*TAILGATE SWITCH	Not Necessary	275.50 FL	*- FL
9	1		*TAILGATE LOCK	Damaged	257.10 FL	*189.50 FL
10	1		*TAILGATE STRIKER LOCK	Not Necessary	97.50 FL	*- FL
11	1		*TAILGATE INNER TRIM BOARD	Mtg Cracked	596.80 FL	*368.20 FL
12	1		*TAILGATE WEATHER STRIP	Necessary	292.30 FL	*162.70 FL
13	1		*SET TAILGATE STOPPERS	Serviceable	60.00 FL	*- FL
14	2		*TAILGATE DAMPER LH / RH	Not Necessary	584.20 FL	*- FL
15	2		*TAILGATE HINGE LH / RH	Not Necessary	196.00 FL	*- FL
16	1		*TAIL LAMP LH / RH	O/S	1,089.20 FL	*462.40 FL
				MtgCracked/N/SNotNecessary		
17	2		*TAIL LAMP PANEL LH / RH	O/S Repair / N/S Not Necessary	550.60 FL	*- FL
18	1		*REAR BUMPER	Distorted	893.70 FL	*497.40 FL
19	2		*REAR BUMPER SIDE RETAINER LH / RH	Serviceable	197.80 FL	*- FL
20	2		*REAR BUMPER TOW HOOK COVER	Serviceable	296.00 FL	*- FL
21	1		*REAR END PANEL	Dented	720.00 FL	*468.00 FL
22	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	160.80 FL	*160.80 FL
23	1		*SPARE WHEEL PANEL	Not Necessary	997.00 FL	*- FL
24	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	194.70 FL	*- FL
25	2		*SPARE WHEEL QUARTER PANEL LH / RH	Not Necessary	625.60 FL	*- FL
26	1		*SPARE WHEEL STYROFOAM TOOL BOX	Not Necessary	320.00 FL	*- FL
27	1		*REAR EXHAUST PIPE	Not Necessary	855.80 FL	*- FL
28	1		*REAR EXHAUST MOUNTING	Not Necessary	56.80 FL	*- FL
29	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	83.50 FL	*- FL
30	1		*REAR EXHAUST MID PIPE	Not Necessary	781.70 FL	*- FL
31	1		*REAR EXHAUST MID PIPE MOUNTING	Not Necessary	56.80 FL	*- FL
32	2		*REAR FENDER LH / RH	Not Necessary	1,918.60 FL	*- FL
33	2		*REAR FENDER INNER SHIELD LH / RH	Not Necessary	187.40 FL	*- FL
34	1		*REAR FENDER INNER TRIM BOARD LH / RH	O/S Cracked / N/S NotNecessary	1,331.20 FL	*398.80 FL
35	2		*REAR FENDER AIR DUCT LH / RH	Not Necessary	192.00 FL	*- FL
36	2		*REAR FENDER QUARTER GLASS MOULDING LH / RH	Not Necessary	350.00 FL	*- FL
37	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
38	1		*TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
39	1		*TAILGATE CENTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*15.00 FS
41	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*15.00 FS
42	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
43	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
45	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*15.00 FS
47	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
48	1		*REAR FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
49	1		*ROCKER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
50	1		*REAR NO PLATE & CASING	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,764.30	3,717.80
- List Item Discount on L Items 20.00/20.00% (S\$)	3,374.86	715.56
Total Parts (S\$)	14,389.44	3,002.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	700.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	150.00	0.00
6	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
7	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	100.00	0.00
8	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	300.00	120.00
9	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	300.00	0.00
10	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
11	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
12	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			6,250.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >