6/28/22, 10:35 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22002474/UEA3Q2

015061042742204PT

32558 km

**Date:** 28/06/2022

Engine No:

Odometer:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100499780

Claimant Vehicle SLJ172S Insured Vehicle No: SLK6968T

No: SL31725 Illistret Verificie No . SLN09001

Date of Loss: 06/03/2022 Nature of Claim: TP Claim No: 6211872980SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLJ172S

Make & Model: LAND ROVER RANGE ROVER EVOQUE, 2.0 TSS

(A)

Reg. Date: 25/11/2016 (Man. Year: 2016) Chassis No: SALVA2AG2GH145152

Colour: Brown

Engine Capacity: 1999 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
Front Right Side: Pirelli 7 mm
Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,801.56	3,974.61	3,826.95	49.05
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,150.00	1,150.00	1,000.00	46.51
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	9,951.56	5,124.61	4,826.95	48.50
	Approved Total (Overridden) (S\$)		4,100.00		
	(S\$)	9,951.56	4,100.00	5,851.56	58.80
	+ GST 7.00/7.00% (S\$)	696.61	287.00	409.61	58.80
	Nett Amount (S\$)	10,648.17	4,387.00	6,261.17	58.80
	+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
		(S\$)	4,815.00		
	Liable Amount (50.00%) (S\$)		2,407.50		
	+ Doc/Search Fee (S\$)		2.00		
	Nett Liability (S\$)		2,409.50		
	Global Sum Settlement (S\$)		2,410.00		

**INSPECTION** 

Date of Assignment: 22/03/2022

Tan Lim Motor Pte Ltd (Defu)

Date Inspected: 22/03/2022 Inspected At: 1 Defu Lane 6

Singapore 539365

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S FRONT DOOR	Repair	2,254.08 FL	*- FL
2	1		*O/S FRONT DOOR GARNISH WITH SILVER MOULDING	Repair	250.50 FL	*- FL
3	1		*O/S FRONT DOOR WEATHERSTRIP	Not Necessary	268.39 FL	*- FL
4	1		*O/S REAR DOOR	Badly Dented	2,654.98 FL	*2,545.00 FL
5	1		*O/S REAR DOOR GARNISH WITH SILVER MOULDING	Bent / Cut	250.50 FL	*250.50 FL
6	1		*O/S REAR DOOR WEATHERSTRIP	Necessary	268.39 FL	*268.39 FL
7	1		*O/S REAR DOOR ARCH	Grazed	315.10 FL	*288.00 FL
8	1		*O/S FRONT DOOR OUTER TOP MOULDING	Not Necessary	175.45 FL	*- FL
9	1		*O/S REAR DOOR OUTER TOP MOULDING	Necessary	175.45 FL	*175.45 FL
10	1		*O/S SPORT RIM REAR	Cut	1,500.00 FS	*800.00 FS
11	1		*O/S TYRE REAR	Serviceable	350.00 FS	*-FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc List Item Discount on L Items 1	Sub Total (S\$) 0.00/10.00% (S\$)	<b>8,462.84</b> 661.28	<b>4,327.34</b> 352.73
				Total Parts (S\$)	7,801.56	3,974.61
			Report was unsubmitted during this print-	out.		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PUTTY AND SPRAY PAINTING O/S FRONT & REAR SIDE DOOR OF THE AFFECTED PORTION	New	900.00	600.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTEN O/S FRONT & REAR SIDE THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	800.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	30.00
4	TO TRANSFER REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	200.00	60.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	20.00
6	REMOVE AND REINSTALL O/S TYRE & RIM	New	50.00	40.00
	Gross Labour	Cost (S\$)	2,150.00	1,150.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >