

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22002477/EPA3Q2**Date:** 01/11/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SKT9026G **Insured Vehicle No :** SLM5251Z

Date of Loss: 12/03/2022 Nature of Claim: TP Claim No: MFL2022D0001542

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT9026G**

Make & Model: LEXUS UX250H, 2.0 (A) Engine No: M20AN160600

Reg. Date: 06/04/2020 (Man. Year: 2020) Chassis No: JTHY65BH202056087

Colour: Silver Odometer: 36741 km

Engine Capacity: 1987 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,275.20	13,348.40	10,926.80	45.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,894.00	10,005.00	4,889.00	32.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	39,169.20	23,353.40	15,815.80	40.38
+ GST 7.00/7.00% (S\$)	2,741.84	1,634.74	1,107.10	40.38
Nett Amount (S\$)	41,911.04	24,988.14	16,922.90	40.38
	+ Medical Costs (S\$)	69.50		
	+ Car Rental (8.0 x S\$150.00/day) (S\$)	1,200.00		
	Nett Liability (S\$)	26,257.64		

INSPECTION

Date of Assignment: 17/03/2022

Date Inspected: 18/03/2022 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2022)
Parts:	M1-SUV	LEXUS UX250H 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT9026G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*50.00 FS
2	1		*SEALANT	Necessary	200.00 FS	*100.00 FS
3	1		*SEAL HOOD TO FR END	Not Necessary	140.90 FS	*- FS
4	1		*GRILLE SUB ASSY	Cut	1,311.00 FS	*1,311.00 FS
5	1		*GARNISH ,RADIATOR	Not Necessary	1,082.90 FS	*- FS
6	1		*GRILLE ,RADIATOR	Not Necessary	225.50 FS	*- FS
7	1		*SUPPORT FR BUMPER	Not Necessary	83.00 FS	*- FS
8	1		*SUPPORT FR BUMPER	Not Necessary	83.00 FS	*- FS
9	1		*RETAINER ,FR BUMPER	Not Necessary	133.20 FS	*- FS
10	1		*ABSORBER ,FR BUMPER	Not Necessary	106.00 FS	*- FS
11	1		*ABSORBER ,FR BUMPER	Not Necessary	148.20 FS	*- FS
12	1		*EXTENSION ,FR	Not Necessary	362.40 FS	*- FS
13	1		*EXTENSION ,FR	Not Necessary	362.40 FS	*- FS
14	2		*TAPE MOULDING NO.1	Necessary	111.00 FS	*111.00 FS
15	1		*SEAL ,RADIATOR TO	Not Necessary	42.50 FS	*- FS
16	1		*SEAL ,RADIATOR TO	Not Necessary	42.50 FS	*- FS
17	1		*BRACKET ,FOG LAMP	Not Necessary	64.20 FS	*- FS
18	1		*BRACKET ,FOG LAMP	Not Necessary	64.20 FS	*- FS
19	1		*COVER ,FOG LAMP ,RH	Not Necessary	145.00 FS	*- FS
20	1		*COVER ,FOG LAMP ,LH	Not Necessary	145.00 FS	*- FS
21	1		*GUARD ,FR BUMPER	Broken	411.10 FS	*411.10 FS
22	1		*BRACKET ,FR BUMPER	Broken	170.70 FS	*170.70 FS
23	1		*RETAINER ,ULTRASONIC	Necessary	44.10 FS	*44.10 FS
24	1		*RETAINER ,ULTRASONIC	Necessary	44.10 FS	*44.10 FS
25	4		*RETAINER ,OUTSIDE	Necessary	16.80 FS	*16.80 FS
26	15		*CLIP	Necessary	40.50 FS	*40.50 FS
27	1		*PANEL SUB-ASSY ,BODY	Not Necessary	921.40 FS	*- FS
28	2		*STOPPER ,RR BUMPER	Not Necessary	16.20 FS	*- FS
29	1		*GLASS SUB-ASSY ,BACK	Necessary	1,395.30 FS	*1,395.30 FS
30	1		*MOULDING ,BACK	Necessary	34.30 FS	*34.30 FS
31	5		*SPACER ,QUARTER	Necessary	31.00 FS	*31.00 FS
32	1		*PANEL SUB-ASSY ,BACK	Dented	6,452.00 FS	*6,452.00 FS
33	1		*W/SCREEN DAM KIT	Necessary	128.50 FS	*128.50 FS
34	2		*SIKA 182010 SIKA TACK GO (BLA)	Necessary	216.00 FS	*216.00 FS
35	1		*SIKA 207 G+P ADHESIVE PRIMER	Necessary	200.00 FS	*200.00 FS
36	1		*PLATE ,BACK DOOR	Not Necessary	151.40 FS	*- FS
37	1		*CAMERA ASSY	Not Necessary	1,358.70 FS	*- FS
38	1		*PLATE ,BACK DOOR	Necessary	72.30 FS	*72.30 FS
39	1		*EMBLEM	Necessary	193.40 FS	*193.40 FS
40	1		*PLATE ,BACK DOOR	Necessary	72.30 FS	*72.30 FS
41	1		*COVER ,DECK TRIM ,RR	Not Necessary	266.20 FS	*- FS
42	1		*RETAINER ,RR BUMPER	Not Necessary	179.30 FS	*- FS
43	1		*RETAINER ,RR BUMPER	Not Necessary	179.30 FS	*- FS
44	1		*REINFORCEMENT	Bent	441.60 FS	*441.60 FS
45	1		*SEAL ,RR BUMPER	Not Necessary	90.10 FS	*- FS
46	1		*SEAL ,RR BUMPER	Not Necessary	90.10 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*COVER ,RR BUMPER	Dented	844.40 FS	*844.40 FS
48	2		*TAPE MOULDING ,NO.1	Necessary	111.00 FS	*111.00 FS
49	1		*COVER ,RR BUMPER	Dented	456.70 FS	*456.70 FS
50	1		*PLATE ,RR BUMPER	Necessary	18.40 FS	*18.40 FS
51	2		*TAPE ,SEAL	Necessary	10.40 FS	*10.40 FS
52	9		*RETAINER ,OUTSIDE	Necessary	37.80 FS	*37.80 FS
53	13		*BUMPER CLIPS	Necessary	55.90 FS	*55.90 FS
54	2		*RETAINER,ULTRANONIC	Necessary	88.20 FS	*88.20 FS
55	2		*RETAINER,ULTRANONIC	Necessary	88.20 FS	*88.20 FS
56	4		*SENSOR ,ULTRASONIC	Not Necessary	1,963.20 FS	*- FS
57	1		*LENS & BODY ,BACK -UP	Not Necessary	202.60 FS	*- FS
58	1		*LENS & BODY ,BACK -UP	Not Necessary	202.60 FS	*- FS
59	1		*RIM ,BAKC -UP RH	Not Necessary	16.00 FS	*- FS
60	1		*RIM ,BAKC -UP LAMP	Not Necessary	16.00 FS	*- FS
61	2		*LED ,RR LAMP RH	Not Necessary	373.00 FS	*- FS
62	1		*REFLECTOR ASSY	Not Necessary	51.60 FS	*- FS
63	1		*REFLECTOR ASSY	Not Necessary	51.60 FS	*- FS
64	1		*COVER ,RR BODY	Not Necessary	320.20 FS	*- FS
65	1		*COVER ,FLOOR UNDER	Not Necessary	170.70 FS	*- FS
66	1		*COVER ,FLOOR UNDER	Not Necessary	170.70 FS	*- FS
67	1		*MOULDING SUB-ASSY	Not Necessary	387.50 FS	*- FS
68	1		*MOULDING SUB-ASSY	Not Necessary	387.50 FS	*- FS
69	2		*CLIP	Necessary	5.40 FS	*5.40 FS
70	1		*REGN PLATE (REAR)	Cut	96.00 FS	*96.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	24,275.20	13,348.40
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING SYSTEM AND FOCUS HEADLAMP	New	216.50	216.50
2	REMOVE/REFIX FRONT PARKING SENSORS	New	216.50	216.50
3	TO CONDUCT ADJUSTMENT ON WAVE RADAR SENSOR	New	216.50	216.50
4	TO CONDUCT ADJUSTMENT ON FRONT CAMERA FOWARD RECOGNITION	New	216.50	216.50
5	REMOVE/REPLACE FRONT BUMPER COVER AND REALIGN	New	1,082.50	866.00
6	SPRAY PAINT ON FRONT BUMPER COVER	New	927.50	742.00
7	SUPPLY REGN PLATE (FRONT)	New	96.00	0.00
8	REMOVE/REFIX REAR WINDSHIELD TO ASSIST REPAIR	New	866.00	866.00
9	INSTALLING SOLAR FILM FOR REAR WINDSHIELD	New	480.00	480.00
10	TRANSFER BACK DOOR COMPONENT AND MECHANISM TO NEW DOOR SHELL	New	866.00	866.00
11	REMOVE/REFIX REVERSE CAMERA	New	216.50	216.50
12	CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE	New	216.50	216.50
13	REMOVE/REFIX REVERSE SENSORS	New	216.50	216.50
14	REMOVE /REFIX REAR LUGGAGE COMPARTMENT INTERIOR TRIM GARNISH TO ASSIST REPAIR	New	433.00	433.00
15	REMOVE ALL NECESSARY PARTS ,TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL ,SPARE WHEEL PAN,R/R AND L/R BODY PANELS ,CUT AND WELD PANEL AND FIT NEW PARTS	New	4,330.00	2,165.00
16	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	4,081.00	1,855.00
17	TO RESET ECU & REPROGRAMME	New	216.50	216.50
Gross Labour Cost (\$\$)			14,894.00	10,005.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >