

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002484/ATY3N2**Date:** 29/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00096892100
Claimant Vehicle No :	GBH72B	Insured Vehicle No :	YQ4110D
Date of Loss:	15/03/2022	Nature of Claim:	TP
		Claim No:	SNM22D201837/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH72B		
Make & Model:	mitsubishi fuso, 3.0 D FE83 (M)	Engine No:	4M42A73400
Reg. Date:	18/09/2009 (Man. Year: 2009)	Chassis No:	FB70BBA20023
Colour:	White	Odometer:	410991 km
Engine Capacity:	2977 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,831.77	2,599.62	5,232.15	66.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	960.00	2,390.00	71.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,181.77	3,559.62	7,622.15	68.17
Approved Total (Overridden) (\$\$)		2,850.00		
Nett Amount (\$\$)	11,181.77	2,850.00	8,331.77	74.51

INSPECTION

Date of Assignment:	17/03/2022	
Date Inspected:	21/03/2022	Inspected At: Polymath Garage Pte Ltd - Kaki Bukit (HQ) 1 Kaki Bukit Avenue 6, #01-15 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Apr 2022)	
Parts:	N/A	mitsubishi fuso 3.0 D FE83 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH72B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	821.50 FL	*- FL
2	2		*FRONT BUMPER BRACKET	Not Necessary	332.20 FL	*- FL
3	1		*FRONT GRILLE	Cracked	559.10 FL	*559.10 FL
4	1		*FRONT GRILLE LOGO	Necessary	55.20 FL	*55.20 FL
5	1		*HEADLAMP	O/s Cracked	1,270.40 FL	*635.20 FL
6	1		*HEADLAMP TOP REFLECTOR	N/s Cracked	130.80 FL	*65.40 FL
7	2		*FRONT SIGNAL LAMP	Not Necessary	455.20 FL	*- FL
8	1		*FRONT PANEL	Repair	1,422.70 FL	*- FL
9	2		*FRONT CORNER PANEL	Dented	1,128.40 FL	*1,128.40 FL
10	1		*WIPER PANEL GARNISH	Cut	562.80 FL	*562.80 FL
11	1		*FRONT WINDSCREEN MOULDING	Not Necessary	240.50 FL	*- FL
12	1		*FRONT LH WING MIRROR (ROUND)	Cracked	112.50 FL	*112.50 FL
13	1		*FRONT LH WING MIRROR STAY	Bent	235.50 FL	*235.50 FL
14	1		*AIR CON BLOWER	Not Necessary	1,156.10 FL	*- FL
15	1		*AIR CON COOLING COIL	Not Necessary	1,607.40 FL	*- FL
16	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
17	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
18	1		*SET FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
19	1		*SET WIPER PANEL GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
20	1		*SET FRONT WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
21	1		*SET FRONT PANEL SEALANT	Not Necessary	60.00 FS	*- FS
22	1		*CANTER STICKER	Necessary	45.40 FL	*45.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,365.70	3,449.50
- List Item Discount on L Items 25.00/25.00% (\$)	2,533.93	849.88
Total Parts (\$)	7,831.77	2,599.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	500.00
2	SPRAY PAINTING	New	1,200.00	400.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	30.00
5	TO REMOVE FRONT WINDSCREEN	New	180.00	0.00
6	TO REMOVE DASHBOARD	New	350.00	0.00
7	TO REMOVE AIRCON SYS & TO TOP UP AIRCON GAS	New	220.00	0.00
Gross Labour Cost (\$\$)			3,350.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >