

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22002485/ETY3N2**Date:** 23/04/2022**REFERENCE**

Insured/Claimant: KIONG KHENG KIAT ANDREW Policy No: MPC21P00071400
Date of Loss: 13/03/2022 Nature of Claim: OD Claim No: DMPC2200105H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ1234G**
Make & Model: MERCEDES-BENZ CLA180, 1.6 AMG (A) Engine No: 27091031591213
Reg. Date: 10/05/2018 (Man. Year: 2018) Chassis No: WDD1179422N643910
Colour: Red Odometer: 90501 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$114,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18
Front Left Side: Continental 4 mm Rear Left Side: Continental 4 mm
Front Right Side: Continental 4 mm Rear Right Side: Continental 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,149.60	10,803.10	346.50	3.11
Miscellaneous Items	685.00	476.00	209.00	30.51
Labour	2,990.00	2,040.00	950.00	31.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,824.60	13,319.10	1,505.50	10.16
Approved Total (Overridden) (S\$)		10,250.00		
(S\$)	14,824.60	10,250.00	4,574.60	30.86
+ GST 7.00/7.00% (S\$)	1,037.72	717.50	320.22	30.86
Nett Amount (S\$)	15,862.32	10,967.50	4,894.82	30.86

INSPECTION

Date of Assignment: 17/03/2022 Present Location: Accord Auto Services Pte Ltd (HQ)
Accord Auto Services Pte Ltd (HQ)
Date Inspected: 17/03/2022 Inspected At: 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047
Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Apr 2022)

Parts: 143 MERCEDES-BENZ CLA180 1.6 AMG (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ1234G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Broken	1,050.00 F	*1,050.00 F
2	1		*FRONT BUMPER RH SIDE RETAINER (WCP)	Broken	25.00 F	*25.00 F
3	1		*FRONT RH BUMPER SENSOR (WCP)	Shorted	120.00 F	*120.00 F
4	1		*FRONT BUMPER CENTER GARNISH (WCP)	Cut	135.00 F	*135.00 F
5	1		*FRONT BUMPER TOW COVER (WCP)	Not Necessary	45.00 F	*- F
6	1		*FRONT BUMPER RH INNER BRACKET (WCP)	Missing	165.00 F	*165.00 F
7	1		*FRONT BUMPER TOP EMBLEM (WCP)	Necessary	55.00 F	*55.00 F
8	1		*FRONT BUMPER SENSOR SEAL (SET) (WCP)	Necessary	36.00 F	*36.00 F
9	1		*FRONT RH FENDER (WCP)	Broken	400.00 F	*400.00 F
10	1		*FRONT RH FENDER SHIELD (WCP)	Torn	115.00 F	*115.00 F
11	1		*FRONT RH FENDER EMBLEM (WCP)	Necessary	80.00 F	*80.00 F
12	1		*FRONT RH HEADLAMP (WCP)	Broken	1,700.00 F	*1,700.00 F
13	1		*FRONT RH HEADLAMP LOWER BRACKET (WCP)	Not Necessary	70.00 F	*- F
14	1		*FRONT RH ABSORBER (WCP)	Bent	400.00 F	*400.00 F
15	1		*FRONT RH ABSORBER MOUNTING (WCP)	Bent	190.00 F	*190.00 F
16	1		*FRONT RH LOWER ARM (WCP)	Bent	280.00 F	*280.00 F
17	1		*FRONT RH LINKAGE (WCP)	Bent	36.00 F	*36.00 F
18	1		*FRONT STABILIZER BAR & BUSH (WCP)	Not Necessary	200.00 F	*- F
19	1		*FRONT RH DRIVE SHAFT(*N/S) (WCP)	Bent	1,350.00 F	*1,350.00 F
20	1		*FRONT RH TIE ROD (WCP)	Bent	73.00 F	*73.00 F
21	1		*FRONT RH TIE ROD END (WCP)	Bent	65.00 F	*65.00 F
22	1		*FRONT RH KNUCKLE WITH WHEEL BEARING (WCP)	Bent	680.00 F	*680.00 F
23	1		*FRONT RH DRIVE SHAFT INNER COVER (WCP)	Torn	60.00 F	*60.00 F
24	1		*FRONT BUMPER UNDER COVER (WCP)	Broken	210.00 F	*210.00 F
25	2		*RIM (WCP)	Cut	1,800.00 F	*1,800.00 F
Supplementary #1						
26	1		*ENGINE UNDER COVER(CENTER) (WCP)	Broken	96.00 F	*96.00 F
27	1		*RH SIDE SKIRT (WCP)	Broken	700.00 F	*700.00 F

Report was unsubmitted during this print-out.

4/23/22, 12:55 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part.						
Sub Total (S\$)					10,136.00	9,821.00
+ Margin on L,N Items 10.00/10.00% (S\$)					1,013.60	982.10
Total Parts (S\$)					11,149.60	10,803.10
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIPS (Necessary)	40.00	30.00
2	1	RH FRONT & REAR FENDER SHIELD CLIPS (Necessary)	75.00	30.00
3	2	TYRE CONTINENTAL RUN FLAT (Torn)(\$520)(80%)	570.00	416.00
Sub Total (\$\$)			685.00	476.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Spray Painting to All Affected Areas (Including Side Skirt & Front RH Door)	New	1,000.00	1,000.00
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	New	1,200.00	500.00
3	Check Wiring System & Light	New	80.00	50.00
4	To Check & Adjust Wheel Aligment	New	80.00	80.00
5	To Remove & Replace Tyre & Rim (Including Tyre Balancing)	New	80.00	60.00
6	To Remove / Replace Undercarriage	New	200.00	200.00
7	Computer Diagnostic Reseting Headlamp , Sensor, Undercarriage & etc... After Repair	New	350.00	150.00
Gross Labour Cost (\$\$)			2,990.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >