

**Accord Auto Services Pte Ltd** (Co.Reg.No:201113141K)10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point  
Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

**ECICS Limited (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC21P00071400	Date of Loss:	13/03/2022
Vehicle Reg. No.:	SLZ1234G	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KIONG KHENG KIAT ANDREW		
Make/Model:	MERCEDES-BENZ CLA180, 1.6 AMG (A)	Vehicle Reg. Date:	10/05/2018
Vehicle Colour:	RED	Chassis No:	WDD1179422N643910
Engine No:	27091031591213		
Odometer:	90501 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	10,274.00
Miscellaneous Items	685.00
Labour	2,990.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$)</b>	<b>13,949.00</b>
<b>+ GST 7.00% (\$)</b>	<b>976.43</b>
<b>Nett Amount (\$)</b>	<b>14,925.43</b>

**This claim is handled by: LAI YEAN KUAN**

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**DETAILS**

ICE

Reference: MRM-SG

Version: 1.0 (Last Synchronised: 17 Mar 2022)

143

MERCEDES-BENZ CLA180 1.6 AMG (A) (Catalogue:Merimen Singapore 1.0)

Repairer's

(Price-denominated Standard List)

Code:

Accord Auto Services Pte Ltd/SLZ1234G/17/03/2022 10:06

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER / OR	0.00	0.00	*1,050.00 F
2	1		*FRONT BUMPER RH SIDE RETAINER / OR	0.00	0.00	*25.00 F
3	1		*FRONT RH BUMPER SENSOR / Shld	0.00	0.00	*120.00 F
4	1		*FRONT BUMPER CENTER GARNISH (RH) - CUT	0.00	0.00	*135.00 F
5	1		*FRONT BUMPER TOW COVER X ?	0.00	0.00	*45.00 F
6	1		*FRONT BUMPER RH INNER BRACKET	0.00	0.00	*165.00 F
7	1		*FRONT BUMPER TOP EMBLEM / MC	0.00	0.00	*55.00 F
8	1		*FRONT BUMPER SENSOR SEAL (SET) / MC	0.00	0.00	*36.00 F
9	1		*FRONT RH FENDER / OR	0.00	0.00	*400.00 F
10	1		*FRONT RH FENDER SHIELD / TN	0.00	0.00	*115.00 F
11	1		*FRONT RH FENDER EMBLEM / MC	0.00	0.00	*80.00 F
12	1		*FRONT RH HEADLAMP / OR	0.00	0.00	*1,700.00 F
13	1		*FRONT RH HEADLAMP LOWER BRACKET ?	0.00	0.00	*70.00 F
14	1		*FRONT RH ABSORBER / BT	0.00	0.00	*400.00 F
15	1		*FRONT RH ABSORBER MOUNTING / BT	0.00	0.00	*190.00 F
16	1		*FRONT RH LOWER ARM / BT	0.00	0.00	*280.00 F
17	1		*FRONT RH LINKAGE / BT	0.00	0.00	*36.00 F
18	1		*FRONT STABILIZER BAR & BUSH / ?	0.00	0.00	*200.00 F
19	1		*FRONT RH DRIVE SHAFT (*N/S) / ?	0.00	0.00	*1,350.00 F
20	1		*FRONT RH TIE ROD / BT	0.00	0.00	*73.00 F
21	1		*FRONT RH TIE ROD END / BT	0.00	0.00	*65.00 F
22	1		*FRONT RH KNUCKLE WITH WHEEL BEARING / BT	0.00	0.00	*680.00 F
23	1		*FRONT RH DRIVE SHAFT INNER COVER / ?	0.00	0.00	*60.00 F
24	1		*FRONT BUMPER UNDER COVER	0.00	0.00	*210.00 F
25	2		*RIM / CUT	0.00	0.00	*1,800.00 F

F=Franchise part.

Sub Total (S\$)	9,340.00
+ Margin on L,N Items 10.00% (S\$)	934.00
<b>Total Parts (S\$)</b>	<b>10,274.00</b>

Accord Auto Services Pte Ltd/SLZ1234G/17/03/2022 10:06. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Particulars	Amount
	<u>Miscellaneous Items</u>	
1	FRONT BUMPER CLIPS / MC	37 40.00
1	RH FRONT & REAR FENDER SHIELD CLIPS / MC	30 75.00
2	TYRE CONTINENTAL RUN FLAT TA (80% of 260)	570.00
Sub Total (\$\$)		685.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
	<u>Labour Items</u>		
1	Spray Painting to All Affected Areas (Including Side Skirt & Front RH Door)	New	1,000.00 ✓
2	Labour Remove / Refix Accident Damages parts to knock, jack, cut weld and realign accident affected area	New	500 1,200.00 ✓
3	Check Wiring System & Light	New	50 80.00 ✓
4	To Check & Adjust Wheel Aligment	New	60 80.00 ✓
5	To Remove & Replace Tyre & Rim (Including Tyre Balancing)	New	200.00 ✓
6	To Remove / Replace Undercarriage	New	150 350.00 ✓
7	Computer Diagnostic Reseting Headlamp, Sensor, Undercarriage & etc... After Repair	New	
Gross Labour Cost (\$\$)			2,990.00

Accord Auto Services Pte Ltd/SLZ1234G/17/03/2022 10:06. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)  
17/3/22, 3.30pm

OD- 11/1 M  
Excess-?  
LIS  
M AL Sy  
6 dys