

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22002491/KEA3Q2**Date:** 02/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210110612
<b>Claimant Vehicle No :</b>	SKR5368G	<b>Insured Vehicle No :</b>	SNC2088C
Date of Loss:	13/03/2022	Nature of Claim:	TP
		Claim No:	0241309133SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKR5368G</b>	Engine No:	1ZR488968
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104526635
Reg. Date:	13/02/2015 (Man. Year: 2015)	Odometer:	115308 km
Colour:	Metallic Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,070.62	637.55	1,433.07	69.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	450.00	870.00	65.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,390.62</b>	<b>1,087.55</b>	<b>2,303.07</b>	<b>67.92</b>
<b>+ GST 7.00/7.00% (S\$)</b>	237.34	76.13	161.21	67.92
<b>Nett Amount (S\$)</b>	<b>3,627.96</b>	<b>1,163.68</b>	<b>2,464.28</b>	<b>67.92</b>
<b>+ Loss of Use (2.0 x S\$60.00/day) (S\$)</b>		120.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,285.68</b>		

INSPECTION

Date of Assignment:	18/03/2022	Ah Lim Motor Company (AMK)
Date Inspected:	18/03/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	2.0 days	

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT EMBLEM	Not Necessary	50.70 FL	*- FL
2	1		*REAR BOOT LOGO COROLLA	Not Necessary	49.10 FL	*- FL
3	1		*REAR BOOT LOGO ALTIS	Not Necessary	49.10 FL	*- FL
4	1		*REAR BOOT RUBBER	Serviceable	175.80 FL	*- FL
5	1		*REAR BOOT LOCK	Repair	399.50 FL	*- FL
6	1		*REAR BOOT LOCK CATCH	Repair	15.30 FL	*- FL
7	1		*REAR BUMPER	Buckled	556.40 FL	*556.40 FL
8	2		*REAR BUMPER UPPER RETAINER LH & RH	Serviceable	218.60 FL	*- FL
9	2		*REAR BUMPER SIDE RETAINER RH & LH	Serviceable	120.80 FL	*- FL
10	6		*REAR BUMPER CLIPS	Necessary	27.00 FL	*27.00 FL
11	1		*REAR BUMPER REINFORCEMENT	Repair	399.50 FL	*- FL
12	2		*REAR BUMPER REINFORCEMENT ARM LH & RH	Repair	136.40 FL	*- FL
13	1		*REAR END PANEL GARNISH	Serviceable	241.90 FL	*- FL
14	2		*REAR END PANEL GARNISH CLIP	Not Necessary	7.40 FL	*- FL
15	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
16	1		*NUMBER PLATE	Serviceable	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,682.50	783.40
- List Item Discount on L Items 25.00/25.00% (\$)	611.88	145.85
Total Parts (\$)	2,070.62	637.55

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REPLACE REAR BUMPER SENSORS	New	60.00	50.00
2	TO SPRAY ANTI RUST COATING ON AFFECTED AREAS	New	60.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS TO KNOCK & REPAIR BOOT,REAR END PANEL ,INNER PANELS AND AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME	New	600.00	200.00
4	TO SPRAY BOOT, REAR BUMPER ,REAR END PANEL	New	600.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>1,320.00</b>	<b>450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >