

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002494/UPA3Q2**Date:** 16/12/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900114388
Claimant Vehicle No :	SKV6491E	Insured Vehicle No :	SLD310S
Date of Loss:	12/03/2022	Nature of Claim:	TP
		Claim No:	4098665407SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV6491E		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2183205A
Reg. Date:	28/09/2015 (Man. Year: 2015)	Chassis No:	SJNFEAJ11U1468649
Colour:	Blue	Odometer:	52088 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	42,001.12	23,014.27	18,986.85	45.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,980.00	6,150.00	4,830.00	43.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	52,981.12	29,164.27	23,816.85	44.95
Approved Total (Overridden) (\$\$)		17,453.00		
Nett Amount (\$\$)	52,981.12	17,453.00	35,528.12	67.06
+ Car Rental (7.0 x S\$100.00/day) (\$\$)		700.00		
+ Other Costs (\$\$)		60.00		
Nett Liability (\$\$)		18,213.00		

INSPECTION

Date of Assignment:	17/03/2022	
Date Inspected:	17/03/2022 Inspected At:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012 Singapore 489977
Estimated Period of Repair:	0.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE: \$46,000.00

LTA REIMBURSEMENT VALUE (RV): \$28,547.00

NETT VALUE: \$17,453.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Broken	1,375.60 FL	*1,375.60 FL
2	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	142.50 FL	*142.50 FL
3	1		*ROOF PANEL	Badly Dented / Buckled	2,393.55 FL	*2,393.55 FL
4	1		*ROOF LINING	Warped	1,982.55 FL	*1,982.55 FL
5	4		*ROOF BRACKET (NPA)	Repair	0.00 FL	*- FL
6	1		*ROOF SIDE MOULDING LH	Necessary	226.40 FL	*226.40 FL
7	1		*ROOF SIDE MOULDING RH	Necessary	226.40 FL	*226.40 FL
8	1		*FRONT DOOR LH	Dented / Bent	1,166.20 FL	*1,166.20 FL
9	1		*FRONT DOOR RUBBER LH	Not Necessary	153.10 FL	*- FL
10	1		*FRONT DOOR STICKER LH	Necessary	39.00 FL	*39.00 FL
11	1		*FRONT DOOR OUTER TOP CHROME MOULDING LH	Bent	200.10 FL	*200.10 FL
12	1		*FRONT DOOR OUTER BOTTOM CHROME MOULDING LH	Bent	76.20 FL	*76.20 FL
13	1		*FRONT DOOR TRIMBOARD LH	*Check	1,460.50 FL	*- FL
14	1		*FRONT DOOR HINGE BOTTOM LH	Serviceable	58.90 FL	*- FL
15	1		*FRONT DOOR HINGE TOP LH	Serviceable	58.90 FL	*- FL
16	1		*FRONT DOOR CHECKER LH	Serviceable	48.20 FL	*- FL
17	1		*FRONT DOOR PILLAR LH	Badly Dented	1,469.00 FL	*1,469.00 FL
18	1		*FRONT DOOR PILLAR RUBBER LH	Deformed	214.90 FL	*214.90 FL
19	1		*WING MIRROR LH	Broken	582.10 FL	*582.10 FL
20	1		*WING MIRROR COVER LH	Broken	112.50 FL	*112.50 FL
21	1		*WING MIRROR SIGNAL LAMP LH	Broken	68.50 FL	*68.50 FL
22	1		*FRONT DOOR GLASS CHAMBER RUBBER LH	Twisted	192.60 FL	*192.60 FL
23	1		*FRONT DOOR OUTER HANDLER LH (BIG)	Cut	173.40 FL	*173.40 FL
24	1		*FRONT DOOR OUTER HANDLER LH (SMALL)	Cut	35.00 FL	*35.00 FL
25	1		*FRONT DOOR REGULATOR GEAR WITH MOTOR LH	Not Necessary	563.60 FL	*- FL
26	1		*FRONT DOOR PROTECTOR LH	Cut	342.60 FL	*342.60 FL
27	1		*FRONT DOOR CENTER PILLAR LH (NPA)	Repair	0.00 FL	*- FL
28	1		*FRONT DOOR LOCK LH	Damaged	172.30 FL	*172.30 FL
29	1		*REAR DOOR LH	Dented / Bent	1,166.20 FL	*1,166.20 FL
30	1		*REAR DOOR TOP CHROME LH	Bent	200.10 FL	*200.10 FL
31	1		*REAR DOOR BOTTOM CHROME LH	Twisted	76.20 FL	*76.20 FL
32	1		*REAR DOOR STICKER LH	Necessary	39.00 FL	*39.00 FL
33	1		*REAR DOOR OUTER HANDLE LH (BIG)	Cut	173.40 FL	*173.40 FL
34	1		*REAR DOOR OUTER HANDLE LH (SMALL)	Cut	35.00 FL	*35.00 FL
35	1		*REAR DOOR PROTECTOR LH	Cut	280.40 FL	*280.40 FL
36	1		*REAR FENDER LH	Dented	1,230.90 FL	*1,230.90 FL
37	1		*REAR FENDER PROTECTOR LH	Grazed	540.50 FL	*540.50 FL
38	1		*TAILLAMP PANEL LH	Repair	361.90 FL	*- FL
39	1		*DASHBOARD	*Check	1,637.90 FL	*- FL
40	1		*BONNET	Bent / Buckled	1,061.30 FL	*1,061.30 FL
41	1		*BONNET HINGE LH	Twisted	59.80 FL	*59.80 FL
42	1		*BONNET HINGE RH	Twisted	59.80 FL	*59.80 FL
43	1		*FRONT FENDER RH	Dented / Bent	753.50 FL	*753.50 FL
44	1		*FRONT FENDER LH	Dented / Bent	753.50 FL	*753.50 FL
45	1		*FRONT FENDER PROTECTOR LH	Grazed	540.50 FL	*540.50 FL
46	1		*FRONT FENDER PROTECTOR RH	Grazed	540.50 FL	*540.50 FL
47	1		*FRONT FENDER SHIELD LH	Torn	128.30 FL	*128.30 FL
48	1		*FRONT FENDER SHIELD RH	Torn	128.30 FL	*128.30 FL
49	1		*SUPPORT PANEL	Repair	588.10 FL	*- FL
50	1		*SUPPORT PANEL INNER SIDE GARNISH LH	Not Necessary	90.20 FL	*- FL
51	1		*FRONT GRILLE	Not Necessary	525.00 FL	*- FL
52	1		*HEADLAMP WITH LOWER BRACKET LH	Cracked	612.20 FL	*612.20 FL
53	1		*FRONT BUMPER	Distorted	682.90 FL	*682.90 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*FRONT BUMPER RETAINER RH	Bent	24.30 FL	*24.30 FL
55	1		*FRONT BUMPER RETAINER LH	Bent	24.30 FL	*24.30 FL
56	1		*FRONT BUMPER BRACKET RH	Not Necessary	193.70 FL	*- FL
57	1		*FRONT BUMPER BRACKET LH	Not Necessary	193.70 FL	*- FL
58	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	755.90 FL	*- FL
59	1		*FRONT BUMPER SPONGE	Not Necessary	240.90 FL	*- FL
60	1		*HEADLAMP RH	*Check	612.20 FL	*- FL
61	1		*ENGINE LOWER DUST COVER	*Check	308.80 FL	*- FL
62	1		*FRONT LOWER ARM LH	*Check	249.40 FL	*- FL
63	1		*FRONT LOWER ARM RH	Bent	249.40 FL	*249.40 FL
64	1		*FRONT ABSORBER MOUNTING RH	*Check	104.00 FL	*- FL
65	1		*FRONT ABSORBER MOUNTING LH	*Check	104.00 FL	*- FL
66	1		*FRONT STABILIZER BAR LINK LH	*Check	36.60 FL	*- FL
67	1		*FRONT STABILIZER BAR LINK RH	Bent	36.60 FL	*36.60 FL
68	1		*FRONT BUMPER LOWER GARNISH (NPA)	Not fitted	0.00 FL	*- FL
69	1		*FRONT DOOR GLASS LH	Shorted	800.00 FS	*800.00 FS
70	1		*REAR DOOR GLASS LH	Cracked	800.00 FS	*800.00 FS
71	1		*REAR FENDER QUARTER GLASS WITH CHROME LH	Not Necessary	400.00 FS	*- FS
72	1		*REAR RIM LH	Cut	1,231.90 FS	*480.00 FS
73	1		*FRONT RIM LH	Cut	1,231.90 FS	*480.00 FS
74	1		*FRONT RIM RH	Cracked	1,231.90 FS	*480.00 FS
75	1		*REAR WHEEL BEARING LH	*Check	346.60 FS	*- FS
76	1		*FRONT BUMPER SENSOR	Not Necessary	280.00 FS	*- FS
77	1		*RADIATOR	Not Necessary	716.10 FS	*- FS
78	1		*AIR CON CONDENSER	Not Necessary	696.90 FS	*- FS
79	1		*RADIATOR COWLING ,FAN AND MOTOR	Not Necessary	635.20 FS	*- FS
80	1		*FRONT TYRE RH	*Check	380.00 FS	*- FS
81	1		*FRONT KNUCKLE ARM LH	*Check	557.00 FS	*- FS
82	1		*FRONT KNUCKLE ARM RH	Bent	557.00 FS	*557.00 FS
83	1		*FRONT SHOCK ABSORBER RH	Bent	560.30 FS	*560.30 FS
84	1		*FRONT SHOCK ABSORBER LH	*Check	560.30 FS	*- FS
85	1		*FRONT ABSORBER STOPPER RH	Not Necessary	46.30 FS	*- FS
86	1		*FRONT ABSORBER STOPPER LH	Not Necessary	46.30 FS	*- FS
87	1		*FRONT WHEEL BEARING LH	*Check	287.50 FS	*- FS
88	1		*FRONT WHEEL BEARING RH	Necessary	287.50 FS	*287.50 FS
89	1		*ENGINE CROSSMEMBER	*Check	612.80 FS	*- FS
90	1		*FRONT DRIVE SHAFT RH	*Check	1,058.20 FS	*- FS
91	1		*FRONT DRIVE SHAFT LH	*Check	1,058.20 FS	*- FS
92	1		*STEERING RACK & PINION	*Check	1,470.80 FS	*- FS
93	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
94	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
95	2		*WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS
96	1		*FRONT DOOR RH (NPA)	Repair	0.00 FS	*- FS
97	1		*FRONT SEAL LH (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 44,894.50 25,073.10
- List Item Discount on L Items 10.00/10.00% (\$\$) 2,893.38 2,058.83

Total Parts (\$\$) 42,001.12 23,014.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON THE AFFECTED AREAS	New	2,800.00	2,000.00
2	ANTI-RUST COATING	New	800.00	180.00
3	WIRING	New	120.00	50.00
4	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
5	TO REMOVE & REFIT CUSHION & UPHOLSTERY	New	500.00	100.00
6	TO REMOVE & REFIT UNDERCARRIAGE	New	800.00	420.00
7	TO REMOVE & REFIT DASHBOARD	New	600.00	250.00
8	TO REMOVE & REFIT ROOF	New	500.00	150.00
9	FOUR WHEEL ALIGNMENT	New	180.00	80.00
10	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	4,500.00	2,800.00
Gross Labour Cost (S\$)			10,980.00	6,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >