



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 8540Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	SCRATCHED	1,985.00	1,288.20
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	144.00	-
1	FRONT BUMPER SIDE RETAINER LH	NOT NECESSARY	112.00	-
1	FRONT BUMPER SIDE COVER LH	NOT NECESSARY	159.00	-
1	FRONT GRILLE	NOT NECESSARY	788.00	-
1	HEADLAMP LH	CRACKED	3,985.00	3,001.75
1	HEADLAMP GARNISH LH	NOT NECESSARY	112.00	-
1	FRONT HEADLAMP LOWER BRACKET	NOT NECESSARY	122.00	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	896.00	-
1	FRONT FENDER COWLING LH	CUT	211.00	171.00
1	FRONT FENDER EMBLEM HYBRID LH	NECESSARY	68.00	68.00
1	FRONT FENDER QUARTER GLASS MOULDING LH	NOT NECESSARY	65.00	-
1	SIDE SKIRTING LH	TO REPAIR SEE LABOUR	898.00	-
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,598.00	-
2	FRONT DOOR HINGES LH @\$112.00	NOT NECESSARY	224.00	-
	LESS 25% DISCOUNT		-2,841.75	-1,132.24
			8,525.25	3,396.71
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	FRONT FENDER COWLING CLIPS (SN)	NECESSARY	50.00	30.00
1	SIDE SKIRTING CLIPS SET (SN)	NECESSARY	50.00	30.00
1	FRONT WHEEL SPORTS RIM LH (SN)	NOT NECESSARY	800.00	-
			980.00	90.00
<u>LABOUR</u>				
	RESET TROUBLE CODE.	NOT NECESSARY	300.00	-
	TO CHECK ELECTRICAL WIRING.		200.00	30.00
	CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	REMOVE AND REFIT FRONT UNDERCARRIAGE LH.	NOT NECESSARY	300.00	-

Report Ref No. CS/INC22002500/Rvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REALIGN HEADLAMP.	NOT NECESSARY	80.00	-
	PANEL BEATING ON AFFECTED AREA. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH, SIDE SKIRTING LH AND FRONT DOOR LH.		800.00	400.00
	SPRAY ON AFFECTED AREA.		800.00	600.00
			2,600.00	1,030.00
GRAND TOTAL			12,105.25	4,516.71
RECOMMENDED COST OF REPAIRS				4,516.71

Report Ref No. CS/INC22002500/Rvy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.