

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002502/AGA3Q2**Date:** 17/08/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700006277
Claimant Vehicle No :	SLN8323A	Insured Vehicle No :	SLN9377M
Date of Loss:	16/03/2022	Nature of Claim:	TP
		Claim No:	9210256848SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8323A	Engine No:	G4FGHU119235
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMHU461858
Reg. Date:	19/05/2017 (Man. Year: 2017)	Odometer:	123386 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,683.44	8,107.28	15,576.16	65.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,700.00	2,640.00	6,060.00	69.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,383.44	10,747.28	21,636.16	66.81
Approved Total (Overridden) (S\$)		8,600.00		
Nett Amount (S\$)	32,383.44	8,600.00	23,783.44	73.44
+ Loss of Use (13.0 x S\$50.00/day) (S\$)		650.00		
Nett Liability (S\$)		9,250.00		

INSPECTION

Date of Assignment:	16/03/2022	
Date Inspected:	16/03/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	475.00 FL	*475.00 FL
2	1		*FRONT BUMPER TOWING COVER	Repair	24.20 FL	*- FL
3	1		*FRONT BUMPER NUMBER PLATE HOLDER	Deformed	110.60 FL	*110.60 FL
4	1		*FRONT BUMPER LOWER LIP	Not Necessary	75.10 FL	*- FL
5	2		*FRONT BUMPER FOGLAMP C/W BRACKET	Not Necessary	589.40 FL	*- FL
6	2		*FRONT BUMPER FOGLAMP GARNISH	Not Necessary	230.80 FL	*- FL
7	2		*FRONT BUMPER SIDE RETAINER	Necessary	93.60 FL	*93.60 FL
8	2		*FRONT BUMPER SIDE LAMP	Cracked	286.20 FL	*286.20 FL
9	1		*FRONT BUMPER REINFORCEMENT	Bent	695.90 FL	*695.90 FL
10	1		*FRONT BUMPER SPONGE	Cracked	110.70 FL	*110.70 FL
11	1		*FRONT BUMPER TOP BEAM	Deformed	198.50 FL	*198.50 FL
12	1		*FRONT BUMPER SIDE BEAM	O/S Damaged	195.80 FL	*97.90 FL
13	1		*FRONT BUMPER LOWER BEAM	Cracked	258.70 FL	*258.70 FL
14	1		*FRONT BUMPER TOP RUBBER	Not Necessary	85.10 FL	*- FL
15	1		*FRONT ENGINE UNDER COVER	Not Necessary	194.60 FL	*- FL
16	2		*FRONT FENDER INNER COWLING	Not Necessary	317.40 FL	*- FL
17	1		*HEAD LAMP	O/S Cracked	3,512.80 FL	*1,756.40 FL
18	2		*HEAD LAMP LOWER BRACKET	Not Necessary	179.20 FL	*- FL
19	1		*CENTER GRILLE	Cracked	460.20 FL	*460.20 FL
20	1		*CENTER GRILLE LOGO	Necessary	109.90 FL	*109.90 FL
21	1		*BONNET	Not Necessary	1,385.00 FL	*- FL
22	1		*BONNET INSULATOR	Not Necessary	221.10 FL	*- FL
23	1		*BONNET LOCK	Not Necessary	129.90 FL	*- FL
24	1		*FRONT SUPPORT PANEL	Cracked	949.30 FL	*949.30 FL
25	2		*FRONT AIRCON CONDENSER SIDE GARNISH	Not Necessary	119.60 FL	*- FL
26	1		*AIRCON CONDENSER	Dented	892.00 FL	*892.00 FL
27	1		*RADIATOR	Not Necessary	516.50 FL	*- FL
28	1		*RADIATOR FAN BLADE, COWLING & MOTOR	Not Necessary	567.80 FL	*- FL
29	1		*WASHER TANK	Not Necessary	96.80 FL	*- FL
30	1		*HORN	Not Necessary	78.70 FL	*- FL
31	1		*REAR BUMPER	Distorted	459.40 FL	*459.40 FL
32	2		*REAR BUMPER MUDFLAP	Not Necessary	192.60 FL	*- FL
33	1		*REAR BUMPER REFLECTOR	O/S Cut	145.00 FL	*72.50 FL
34	1		*REAR BUMPER LOWER LIP	Deformed	260.10 FL	*260.10 FL
35	2		*REAR BUMPER RETAINER	Necessary	56.60 FL	*56.60 FL
36	1		*REAR BUMPER REINFORCEMENT	Bent	303.70 FL	*303.70 FL
37	1		*REAR BUMPER BRACKET	O/S Bent	38.00 FL	*19.00 FL
38	2		*REAR BUMPER INNER LOWER GARNISH	Not Necessary	98.40 FL	*- FL
39	1		*REAR FENDER RH	Not Necessary	1,768.30 FL	*- FL
40	1		*REAR FENDER AIR VENT RH	Not Necessary	29.10 FL	*- FL
41	2		*REAR FENDER INNER COWLING	Not Necessary	96.60 FL	*- FL
42	2		*REAR FENDER INNER TRIM	Not Necessary	343.40 FL	*- FL
43	1		*REAR WINDSCREEN MOULDING	Not Necessary	72.00 FL	*- FL
44	1		*TAILLAMP	O/S Cracked	725.20 FL	*362.60 FL
45	2		*TAILLAMP PANEL	Not Necessary	344.00 FL	*- FL
46	1		*BOOTLID	Repair	1,672.80 FL	*- FL
47	2		*BOOTLID LAMP	Not Necessary	597.60 FL	*- FL
48	2		*BOOTLID NUMBER PLATE LAMP	Not Necessary	36.00 FL	*- FL
49	1		*BOOTLID LOGO	Necessary	32.10 FL	*32.10 FL
50	1		*BOOTLID EMBLEM S	Necessary	37.60 FL	*37.60 FL
51	1		*BOOTLID EMBLEM ELANTRA	Necessary	62.80 FL	*62.80 FL
52	1		*BOOTLID OUTER SWITCH BUTTON	Not Necessary	321.20 FL	*- FL
53	1		*BOOTLID DETECTOR (OUTER)	Not Necessary	396.40 FL	*- FL
54	1		*BOOTLID DETECTOR (INNER)	Not Necessary	372.10 FL	*- FL
55	2		*BOOTLID HINGE	Not Necessary	188.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	2		*BOOTLID STOPPER	Not Necessary	38.40 FL	*- FL
57	1		*BOOTLID INSULATOR	Not Necessary	85.40 FL	*- FL
58	1		*BOOTLID TOP LOCK	Not Necessary	134.60 FL	*- FL
59	1		*BOOTLID LOWER LOCK	Not Necessary	19.10 FL	*- FL
60	1		*BOOTLID WEATHERSTRIP	Not Necessary	89.60 FL	*- FL
61	1		*REAR END PANEL	Dented	385.70 FL	*385.70 FL
62	1		*REAR END PANEL TOP GARNISH	Deformed	70.10 FL	*70.10 FL
63	1		*REAR FLOOR PANEL TOP BOARD	Deformed	214.00 FL	*214.00 FL
64	1		*REAR TOOLS SPONGE	Not Necessary	154.80 FL	*- FL
65	1		*REAR SPARE TYRE BOLT	Not Necessary	35.40 FL	*- FL
66	1		*REAR CHASSIS RH	Not Necessary	1,694.10 FL	*- FL
67	1		*REAR EXHAUST PIPE	Bent	943.90 FL	*688.00 FL
68	1		*REAR EXHAUST INSULATOR	Not Necessary	98.50 FL	*- FL
69	1		*SET REAR EXHAUST GASKET	Necessary	60.00 FL	*40.00 FL
70	2		*REAR EXHAUST MOUNTING	Not Necessary	39.60 FL	*- FL
71	1		*FRONT NUMBER PLATE	Dented	80.00 FS	*50.00 FS
72	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
73	1		*SET FRONT BUMPER FOGLAMP GARNISH CLIP	Not Necessary	30.00 FS	*- FS
74	1		*SET FRONT ENGINE UNDER COVER CLIP	Not Necessary	50.00 FS	*- FS
75	1		*SET CENTER GRILLE CLIP	Necessary	30.00 FS	*20.00 FS
76	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	50.00 FS	*- FS
77	1		*SET FRONT AIRCON CONDENSER SIDE GARNISH CLIP	Not Necessary	30.00 FS	*- FS
78	1		*BONNET SEALANT	Not Necessary	150.00 FS	*- FS
79	1		*SET BONNET INSULATOR CLIP	Not Necessary	60.00 FS	*- FS
80	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
81	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
82	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
83	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
84	1		*SET REAR BUMPER INNER LOWER GARNISH CLIP	Not Necessary	40.00 FS	*- FS
85	1		*BOOTLID SEALANT	Not Necessary	80.00 FS	*- FS
86	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
87	1		*SET TAIL LAMP CLIP	O/S Necessary	40.00 FS	*20.00 FS
88	1		*TAILLAMP PANEL RH SEALANT	Not Necessary	60.00 FS	*- FS
89	1		*REAR FENDER RH SEALANT	Not Necessary	150.00 FS	*- FS
90	1		*REAR FENDER INNER PANEL SEALANT RH	Not Necessary	150.00 FS	*- FS
91	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
92	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
93	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	80.00 FS	*- FS
94	1		*REAR WINDSCREEN GLASS INNER SHIELD	Not Necessary	60.00 FS	*- FS
95	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
96	1		*REAR END PANEL INSULATION SEALANT	Necessary	150.00 FS	*60.00 FS
97	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
98	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
99	1		*FRONT FENDER RH	Not Necessary	456.10 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **28,949.30** **10,019.10**
- List Item Discount on L Items 20.00/20.00% (\$\$) 5,265.86 1,911.82

Total Parts (\$\$) **23,683.44** **8,107.28**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS (FRONT)	New	1,400.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA (FRONT)	New	1,400.00	200.00
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS (FRONT)	New	120.00	60.00
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST (FRONT)	New	80.00	0.00
5	REFOCUS HEADLAMP BEAM (FRONT)	New	60.00	0.00
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC (FRONT)	New	180.00	0.00
7	PANEL BEATING, REMOVAL AND REPLACING PARTS (REAR)	New	1,800.00	600.00
8	TO SPRAY PAINT AFFECTED AREA (REAR)	New	1,600.00	800.00
9	TUFF COAT (REAR)	New	250.00	60.00
10	WIRING CHECK (REAR)	New	180.00	30.00
11	REMOVE AND REFIX UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR (REAR)	New	350.00	60.00
12	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING (REAR)	New	80.00	50.00
13	REAR CHASSIS ALIGNMENT (REAR)	New	250.00	0.00
14	TRANSFER BOOTLID MECHANISM (REAR)	New	80.00	0.00
15	CONDUCT WATER LEAKAGE TEST (REAR)	New	80.00	0.00
16	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT (REAR)	New	80.00	0.00
17	REMOVE AND REFIX REAR EXHAUST PIPE (REAR)	New	180.00	80.00
18	TRANSFER REAR DOOR MECHANISM (REAR)	New	80.00	0.00
19	REMOVE AND REFIX REAR WINDSCREEN GLASS (REAR)	New	120.00	0.00
20	REMOVE AND REFIX REVERSE CAMERA (REAR)	New	80.00	0.00
21	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC (REAR)	New	250.00	0.00
Gross Labour Cost (\$)			8,700.00	2,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >