

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22002504/UVY3N2**Date:** 06/04/2022**REFERENCE**

Insured/Claimant: LIM YOW LONG Policy No: DMPCSNW0014062106

Date of Loss: 15/03/2022 Nature of Claim: OD Claim No: SNM22D201833/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKT8988L**

Make & Model: MERCEDES-BENZ R300L, 3.0 (A)

Reg. Date: 19/01/2012 (Man. Year: 2011)

Colour: Grey

Engine Capacity: 2996 cc

Market Value/New Car Price: S\$108,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 27294531942634

Chassis No: WDC2511542A139303

Odometer: 238841 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55R18

Front Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Tyre Size: 255/55R18

Rear Left Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	45,635.45	18,823.04	26,812.41	58.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,350.00	2,660.00	3,690.00	58.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	51,985.45	21,483.04	30,502.41	58.67
Approved Total (Overridden) (S\$)		15,000.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	50,485.45	13,500.00	36,985.45	73.26
+ GST 7.00/7.00% (S\$)	3,533.98	945.00	2,588.98	73.26
Nett Amount (S\$)	54,019.43	14,445.00	39,574.43	73.26

INSPECTION

Date of Assignment: 17/03/2022

Date Inspected: 18/03/2022 Inspected At:

Estimated Period of Repair: 7.0 days

Kim Chwee Auto Pte Ltd (HQ)

1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki

Bukit

Singapore 417883

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2022)
Parts:	M1-SUV	MERCEDES-BENZ R300L 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT8988L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER LOGO	Not Necessary	46.00 FL	*- FL
2	1		*FRONT BUMPER	Torn	2,450.00 FL	*2,029.38 FL
3	1		*FRONT BUMPER AIR GRILLE	Not Necessary	182.00 FL	*- FL
4	1		*FRONT FOG LAMP COVER RH	Not Necessary	56.00 FL	*- FL
5	2		*FRONT BUMPER CORNER SENSOR SEAL RH	Necessary	14.00 FL	*14.00 FL
6	2		*FRONT BUMPER CORNER PARKING SENSOR RH	Not Necessary	470.00 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	15.00 FL	*15.00 FL
8	1		*FRONT BUMPER TOP SEAL	Not Necessary	84.00 FL	*- FL
9	1		*FRONT BUMPER SPONGE	Not Necessary	155.00 FL	*- FL
10	1		*HEAD LAMP ASSY RH	Cracked	3,640.00 FL	*1,272.52 FL
11	1		*FRONT FENDER RH	Distorted	1,425.00 FL	*1,329.50 FL
12	1		*FRONT FENDER INNER SHIELD RH NO1	Torn	119.00 FL	*119.00 FL
13	1		*FRONT FENDER INNER SHIELD RH NO2	Torn	189.00 FL	*189.00 FL
14	1		*ROCKER PANEL GARNISH (SIDE SKIRT) RH	Not Necessary	609.00 FL	*- FL
15	10		*ROCKET PANEL CLIP	Not Necessary	52.00 FL	*- FL
16	1		*FRONT DOOR GLASS RH	Cut	630.00 FL	*520.00 FL
17	1		*FRONT DOOR RH	Dented/Warped	2,520.00 FL	*2,520.00 FL
18	1		*FRONT DOOR RUBBER RH	Necessary	416.00 FL	*305.00 FL
19	1		*FRONT DOOR FRAME TOP SEAL RH	Necessary	97.00 FL	*97.00 FL
20	1		*FRONT DOOR BOTTOM SEAL RH	Necessary	23.00 FL	*23.00 FL
21	1		*FRONT DOOR GLASS MOULDING RH (OUTER)	Bent	195.00 FL	*165.00 FL
22	1		*FRONT DOOR GLASS CHANNEL RH	Not Necessary	145.00 FL	*- FL
23	1		*FRONT DOOR WING MIRROR ASSY RH	Broken	2,485.00 FL	*1,182.39 FL
24	1		*FRONT DOOR WING MIRROR GLASS RH	Broken	585.00 FL	*380.00 FL
25	1		*FRONT DOOR WING MIRROR COVER RH	Broken	225.00 FL	*182.00 FL
26	1		*FRONT DOOR TOP CHROME MOULDING	Necessary	97.00 FL	*97.00 FL
27	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	375.00 FL	*- FL
28	1		*FRONT DOOR PROTECTOR RH	Necessary	256.00 FL	*256.00 FL
29	1		*FRONT DOOR INNER LOCK RH	Not Necessary	1,425.00 FL	*- FL
30	1		*FRONT DOOR BOARD RH	Not Necessary	985.00 FL	*- FL
31	1		*FRONT DOOR RUBBER RH	Repeated	315.00 FL	*- FL
32	1		*REAR DOOR RUBBER SEAL (BEHIND FRONT DOOR)	Not Necessary	71.50 FL	*- FL
33	1		*REAR DOOR GLASS CHANNEL RH	Not Necessary	145.00 FL	*- FL
34	1		*REAR DOOR GLASS OUTER MOULDING	Not Necessary	195.00 FL	*- FL
35	1		*REAR DOOR FRAME TOP CHROME MOULDING RH	Not Necessary	375.00 FL	*- FL
36	1		*REAR DOOR QUARTER GLASS RUBBER RH	Not Necessary	115.00 FL	*- FL
37	1		*REAR DOOR QUARTER GLASS PILLAR RH	Not Necessary	75.00 FL	*- FL
38	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	375.00 FL	*- FL
39	1		*REAR DOOR RUBBER RH	Not Necessary	315.00 FL	*- FL
40	1		*REAR DOOR PROTECTOR RH	Necessary	256.00 FL	*256.00 FL
41	1		*REAR BUMPER	Distorted	2,550.00 FL	*2,118.25 FL
42	1		*REAR BUMPER DIFFUSER	Not Necessary	465.00 FL	*- FL
43	1		*REAR BUMPER SIDE RETAINER	Not Necessary	48.00 FL	*- FL
44	1		*REAR BUMPER REFLECTOR RH	Not Necessary	23.00 FL	*- FL
45	1		*REAR BUMPER REVERSING SENSOR RH	Not Necessary	235.00 FL	*- FL
46	1		*REAR FENDER RH	Badly Dented	8,136.00 FL	*6,800.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FENDER QUARTER GLASS ASSY RH	Not Necessary	665.00 FL	*- FL
48	1		*FRONT LOWER ARM RH	Not Necessary	685.00 FL	*- FL
49	1		*FRONT SHOCK ABSORBER RH	Not Necessary	2,548.00 FL	*- FL
50	1		*FRONT KNUCKLE ARM RH	Not Necessary	780.00 FL	*- FL
51	1		*FRONT TOP ARM RH	Not Necessary	395.00 FL	*- FL
52	1		*FRONT WHEEL BEARING WITH HUB	Not Necessary	525.00 FL	*- FL
53	1		*REAR LOWER ARM RH	Not Necessary	645.00 FL	*- FL
54	1		*REAR KNUCKLE ARM RH	Not Necessary	695.00 FL	*- FL
55	1		*REAR WHEEL BEARING WITH HUB RH	Not Necessary	525.00 FL	*- FL
56	1		*REAR SHOCK ABSORBER RH	Not Necessary	2,548.00 FL	*- FL
57	1		*REAR CONTROL ARM RH	Not Necessary	685.00 FL	*- FL
58	1		*REAR TOP ARM RH	Not Necessary	395.00 FL	*- FL
59	2		*TYRE	Serviceable	1,500.00 FS	*- FS
60	1		*FRONT DOOR GLASS SOLAR FILM	Necessary	180.00 FS	*100.00 FS
61	1		*SET REAR FENDER QUARTER GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
62	1		*FRONT SPORT RIM RH	Cut	1,800.00 FS	*800.00 FS
63	1		*REAR SPORT RIM RH	Not Necessary	1,800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	50,110.50	20,810.04
- List Item Discount on L Items 10.00/10.00% (\$\$)	4,475.05	1,987.00
Total Parts (\$\$)	45,635.45	18,823.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING & DIAGNOSTIC FAULT CODE	New	200.00	80.00
2	REMOVE & REFIX REAR FENDER QUARTER GLASS	New	150.00	100.00
3	REMOVE & REFIX CUSHION SEAT	New	250.00	100.00
4	LABOUR CHARGE TO REMOVE & REFIX & RENEW PARTS CUT & WELDING ETC	New	2,200.00	1,100.00
5	REMOVE & REFIX & RENEW FRONT & REAR UNDER CARRIAGE,SUSPENSION ETC	New	1,200.00	0.00
6	CHECK 4 WHEEL ALIGNMENT	New	150.00	80.00
7	TO RESPRAY PAINTING	New	2,200.00	1,200.00
Gross Labour Cost (S\$)			6,350.00	2,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >