

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG122002517/KTY3N2**Date:** 25/05/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SMH6124R**Insured Vehicle No :** SLZ686S

Date of Loss: 17/03/2022

Nature of Claim:

TP

Claim No: CDMPG22000479

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMH6124R**

Make &amp; Model: RENAULT GRAND SCENIC, 1.5 D Ci (A)

Engine No: K9KF649D059502

Reg. Date: 28/01/2019 (Man. Year: 2018)

Chassis No: VF1RFA00561924964

Colour: White

Odometer: 227427 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R20

Rear Tyre Size:

195/55 R20

Front Left Side: Tourador 7 mm

Rear Left Side:

Tourador 8 mm

Front Right Side: Tourador 7 mm

Rear Right Side:

Tourador 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	34,644.14	11,403.17	23,240.97	67.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,550.00	2,470.00	3,080.00	55.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>40,194.14</b>	<b>13,873.17</b>	<b>26,320.97</b>	<b>65.48</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>11,000.00</b>		
<b>(S\$)</b>	40,194.14	11,000.00	29,194.14	72.63
<b>+ GST 7.00/7.00% (S\$)</b>	2,813.59	770.00	2,043.59	72.63
<b>Nett Amount (S\$)</b>	<b>43,007.73</b>	<b>11,770.00</b>	<b>31,237.73</b>	<b>72.63</b>

INSPECTION

Date of Assignment: 17/03/2022

Date Inspected: 21/03/2022

Inspected At:

Munich Autocare Pte Ltd (HQ)

60 Jalan Lam Huat, #07-43

Singapore 737869

Estimated Period of Repair: 10.0 days

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2022)
<b>Parts:</b>	M1-MPV	RENAULT GRAND SCENIC 1.5 D Ci (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMH6124R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE OUTER PANEL GS4 (GARNISH)	Cracked	750.84 F	*750.84 FL
2	1	*TAILGATE ASSY	Repair	2,697.26 F	*- FL
3	1	*EMBLEM DIAMOND	Necessary	272.73 F	*142.60 FL
4	1	*LETTERING RENAULT	Necessary	186.62 F	*72.40 FL
5	1	*LETTERING SCENIC	Necessary	217.20 F	*117.50 FL
6	1	*REVERSE CAMERA GS4	Serviceable	814.68 F	*- FL
7	1	*TAILGATE LOCK CATCHER	Repair	140.06 F	*- FL
8	1	*TAILGATE LOCK ASSY GS4 M4S	Repair	137.16 F	*- FL
9	1	*REAR TAIL LAMP RH	Serviceable	559.44 F	*- FL
10	1	*REAR TAIL LAMP LH	Serviceable	559.44 F	*- FL
11	1	*REAR TAIL GATE LAMP LH	Serviceable	559.44 F	*- FL
12	1	*REAR TAIL GATE WEATHERSTRIP	Serviceable	399.96 F	*- FL
13	2	*TAILGATE HINGE LH/RH	Repair	792.28 F	*- FL
14	2	*TAILGATE DAMPER L&R GS4 S4	Serviceable	473.76 F	*- FL
15	1	*TAILGATE OUTER PANEL MOULDING STRIP	Serviceable	564.00 F	*- FL
16	1	*REAR BOOT COMPARTMENT BOARD	Serviceable	671.52 F	*- FL
17	1	*REINFORCEMENT REAR PANEL GS4	Bent	900.60 F	*900.60 FL
18	1	*REINFORCEMENT REAR INNER PANEL GS4	Repair	429.72 F	*- FL
19	1	*REAR END PANEL INNER GARNISH	Serviceable	264.00 F	*- FL
20	1	*MBR PRE ASSY SIDE ,RR RH	Repair	1,114.20 F	*- FL
21	1	*SPARE TYRE PANEL	Cracked	1,436.16 F	*987.00 FL
22	1	*REAR BUMPER LOWER REFLECTOR LH	Serviceable	415.20 F	*- FL
23	1	*BUMPER REAR GS4 BOSS	Cracked	1,113.60 F	*1,113.60 FL
24	1	*REAR BUMPER PAD LOWER (BLACK)	Cracked	666.36 F	*666.36 FL
25	1	*REAR BUMPER LOWER (SIVER)	Bent	579.84 F	*579.84 FL
26	1	*REAR BUMPER REINFORCEMENT	Bent	767.04 F	*685.60 FL
27	1	*REAR BUMPER LOWER PAD SUPPORT CTE	Serviceable	97.44 F	*- FL
28	1	*REAR BUMPER LOWER SUPPORT LH	Cracked	127.20 F	*127.20 FL
29	1	*REAR BUMPER LOWER SUPPORT LH	Cracked	127.20 F	*127.20 FL
30	1	*REAR BUMPER CENTER GARNISH	Serviceable	399.60 F	*- FL
31	1	*REAR BUMPER SENSOR HARNESS	Torn	231.84 F	*231.84 FL
32	1	*BUMPER REAR BRACKET LH GS4	Repair	322.44 F	*- FL
33	1	*BUMPER REAR BRACKET RH GS4	Repair	322.44 F	*- FL
34	1	*BUMPER RR RH UNDER COVER GS4	Cracked	334.92 F	*334.92 FL
35	1	*BUMPER RR LH UNDER COVER GS4	Cracked	334.92 F	*334.92 FL
36	4	*REAR REVERSE SENSOR	Cracked / Missing	1,166.40 F	*904.00 FL
37	2	*BLIND SPOT SENSOR	Serviceable	916.32 F	*- FL
38	1	*EXHAUST PIPE REAR SILENCER GS4	Repair	1,083.60 F	*- FL
39	1	*EXHAUST CLAMP X50 M4 2.0 T2	Serviceable	116.24 F	*- FL
40	1	*EXHAUST HEAT SHIELD REAR END	Bent	321.96 F	*321.96 FL
41	1	*EXHAUST HEAT SHIELD OUTER	Bent	219.36 F	*219.36 FL
42	6	*RIVET FIX P	Necessary	64.80 F	*64.80 FL
43	10	*RIVET SILVER	Necessary	84.00 F	*84.00 FL
44	1	*FRONT BUMPER	Buckled	1,894.49 F	*1,461.70 FL
45	1	*BUMPER BRACKET LH	Repair	200.98 F	*- FL
46	1	*BUMPER BRACKET RH	Repair	200.98 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
47	1	*BUMPER REINFORCEMENT PLASTIC	Serviceable	310.83 F	*- FL
48	1	*RADIATOR GRILLE	Cracked	615.94 F	*487.00 FL
49	1	*RADIATOR GRILLE TOP GARNISH (BLACK)	Serviceable	344.50 F	*- FL
50	1	*EMBLEM	Cracked	217.00 F	*108.00 FL
51	1	*FRONT SUPPORT PANEL	Repair	1,578.59 F	*- FL
52	1	*BONNET	Repair	1,698.84 F	*- FL
53	1	*FRONT CENTRE BRACE BRACKET	Repair	191.40 F	*- FL
54	1	*RADIATOR GRILLE CHROME MOULDING	Cracked	502.86 F	*368.00 FL
55	1	*REAR TAIL GATE LAMP RH	Serviceable	559.44 F	*- FL
56	6	*REAR BUMPER CLIPS	Necessary	42.00 FS	*42.00 FS
57	1	*SET REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	Not Necessary	35.00 FS	*- FS
58	1	*REAR FLOOR PANEL SEALAT	Not Necessary	35.00 FS	*- FS
59	1	*REAR END PANEL SEALANT	Necessary	35.00 FS	*30.00 FS
60	10	*SET REAR TAILGATE OUTER GARNISH CLIPS	Necessary	70.00 FS	*70.00 FS
61	6	*REAR TAIL GATE TRIM CLIP	Not Necessary	42.00 FS	*- FS
62	1	*REAR NUMBER PLATE WITH CASING	Serviceable	60.00 FS	*- FS
63	1	*REAR WEATHER SHIELD GUM PAINT & COATING	Not Necessary	25.00 FS	*- FS
64	6	*FRONT BUMPER CLIPS	Necessary	42.00 FS	*42.00 FS
65	1	*FRONT HEADLAMP RH	Mtg Cracked	1,204.00 F	*1,057.00 FL
66	1	*REAR BUMPER REINFORCEMENT	Repeated	767.00 F	*- FL
67	1	*REAR BUMPER ANTENNA ELECTRICAL	Dented	94.50 F	*94.50 FL
68	1	*REAR BUMPER ANTENNA ELECTRICAL HARNESS WIRE	Torn	123.00 F	*123.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>34,644.14</b>	<b>12,649.74</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	1,246.57
<b>Total Parts (\$\$)</b>	<b>34,644.14</b>	<b>11,403.17</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEATING ,REALIGN DISMANTLE REAR BUMPER ,REAR BOOT LID ,END PANEL OUTER,FRONT BUMPER ,AND ALL NECESSARY ETC	New	2,000.00	1,200.00
2	TO CHECK ELECTRICAL WIRING SYSTEM OF REAR SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF REAR TAIL GATE LAMP & TAIL LAMP LH/RH	New	80.00	20.00
3	TO DISMANTLE & RENEW REAR REVERSE SENSOR & FRONT PARKING SENSOR	New	280.00	120.00
4	TO REMOVE AND REFIX REAR REVERSE SENSOR AND FRONT PARKING SENSOR WIRE HARDESS	New	280.00	0.00
5	TO REMOVE & INSTALL LUGGAGE COMPARTMENT AND SIDE FENDER INNER TRIM TO ACILITATE REPAIR	New	120.00	80.00
6	TO PUTTY & RESPRAY PAINTING REAR BUMPER ,REAR BOOT LID END PANEL CHASSIS LH/RH FRONT BUMPER ,BONNET AND ALL NECESSARY ETC	New	1,800.00	1,000.00
7	TO TEST WATER SEEPAGE REAR SCREEN & SUNROOF WATER LEAKAGE	New	200.00	0.00
8	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	0.00
9	TO CONDUCT RE-PROGRAMME AND RESETTING OF REVERSE SYSTEM FAULT CODE	New	350.00	0.00
10	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	120.00	30.00
11	TO TRANSFER REAR TAIL GATE MECHANISM	New	120.00	0.00
12	TO CHECK ELECTRICAL WIRING SYSTEM OF ADJUSTMENT OF FRONT HEADLAMP LH/RH	New	80.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,550.00</b>	<b>2,470.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >