



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2203537

INV Date 09/06/2022

Reference CC4/LPC22002521/Ega3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 3418H
Insured Veh. YN 8626Y
Claim No. 21/21/22/VC00/025563
Policy No. Z/21/VC00/111875
Accident Date 18/12/2021
Inspection Date 18/03/2022

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC22002521/Ega3q2 Date: 09/06/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 8626Y	Veh. Inspected	GBJ 3418H	
Policy No.	Z/21/VC00/111875	Coverage (\$)	0.00	
Claim No.	21/21/22/VC00/025563	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	17/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JN1MC2E26Z0030991	Colour	ORANGE	
Odometer	102915 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	DUNLOP	4 mm	
L/H Front Tyre	195 R15C	DUNLOP	4 mm	
R/H Rear Tyre	195 R15C	DUNLOP	4 mm	
L/H Rear Tyre	195 R15C	DUNLOP	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/12/2021	Inspection Date	18/03/2022	
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 3418H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	DENTED	1,998.30	1,998.30
1	TAILGATE WINDSCREEN SEAL	NECESSARY	141.20	141.20
1	TAILGATE LOCK	NOT NECESSARY	262.30	-
1	TAILGATE RUBBER	NOT NECESSARY	173.20	-
1	TAIL LAMP RH	NOT NECESSARY	311.50	-
1	REAR BUMPER	NOT NECESSARY	632.70	-
10	REAR BUMPER CLIPS	NOT NECESSARY	50.00	-
1	REAR BUMPER SIDE BRACKET RH	NOT NECESSARY	17.50	-
1	REAR BUMPER STOPPER RH	NOT NECESSARY	35.40	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	244.30	-
1	REAR END PANEL (OUTER)	NOT NECESSARY	247.10	-
1	REAR END PANEL (INNER)(NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-411.35	-213.95
			3,702.15	1,925.55
<u>SPECIAL NETT ITEMS</u>				
1	WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
1	END PANEL SEALANT (SN)	NOT NECESSARY	40.00	-
1	LTA STICKER (70KM/H)(SN)	NECESSARY	10.00	10.00
1	LTA STICKER 8 PAX (SN)	NECESSARY	10.00	10.00
			300.00	60.00
<u>LABOUR</u>				
	LABOUR TO CARRY OUT REAR REPAIR.INCLUSIVE OF THE REPAIR OF REAR END PANEL (INNER).		800.00	200.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		35.00	35.00
	TO SPRAY PAINTING ON REAR AFFECTED AREA.		700.00	200.00
	SPRAY RUST PROOF ON AFFECTED AREA.		50.00	30.00
	TO REMOVE & INSTALL ALL TAILGATE FITTING.		100.00	50.00
	TO REMOVE & INSTALL REAR TAILGATE GLASS.		150.00	120.00

Report Ref No. CC4/LPC22002521/Ega3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DETACH & RENEW REVERSE SENSOR.	NOT NECESSARY	60.00	-
			1,895.00	635.00
GRAND TOTAL			5,897.15	2,620.55
RECOMMENDED COST OF REPAIRS				2,620.55

Report Ref No. CC4/LPC22002521/Ega3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 3418H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 3418H

RE-INSPECTION

