

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ETHOZ

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 17/03/2022
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D21MTHCVE001595 Accident Date : 18/12/2021
Vehicle No : GBJ-3418-H Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Nett Item			
1	TAILGATE / 00	1,998.30	
1	TAILGATE WINDSCREEN SEAL / n/c	141.20	
1	TAILGATE LOCK X	262.30	
1	TAILGATE RUBBER X	173.20	
1	TAIL LAMP RH X	311.50	
1	REAR BUMPER X	632.70	
10	REAR BUMPER CLIPS X	50.00	
1	REAR BUMPER SIDE BRACKET RH X	17.50	
1	REAR BUMPER STOPPER RH X	35.40	

Date : 17/03/2022
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D21MTHCVE001595

Accident Date : 18/12/2021

Vehicle No : GBJ-3418-H

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR BUMPER REINFORCEMENT X	244.30	
1	REAR END PANEL (OUTER) X	247.10	
1	REAR END PANEL (INNER) X		
	RESTORE		
	Sub Total	4113.50	
	Discount 10% On Parts	(411.35)	
	<u>Special Nett Item</u>		
1	WINDSCREEN SEALANT / MC	40.00	
1	REVERSE SENSOR X	200.00	
1	END PANEL SEALANT X	40.00	
1	LTA STICKER (70 KM/H) / MC	10.00	

Date : 17/03/2022
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D21MTHCVE001595

Accident Date : 18/12/2021

Vehicle No : GBJ-3418-H

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	LTA STICKER 8 PAX / <i>NE</i>	10.00	
	Sub Total	300.00	
Labour & Misc			
	LABOUR TO CARRY OUT REAR REPAIR	800.00	<i>290</i>
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	<i>/</i>
	TO SPRAY PAINTING ON REAR AFFECTED AREA	700.00	<i>200</i>
	SPRAY RUST PROOF ON AFFECTED AREA	50.00	<i>30</i>
	TO REMOVE & INSTALL ALL TAILGATE FITTING	100.00	<i>50</i>
	TO REMOVE & INSTALL REAR TAILGATE GLASS	150.00	<i>120</i>

Steve CLKK)
18/3/22, 1.00pm

WL PL
3 LG
L/S
hy PL hy

Date : 17/03/2022
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D21MTHCVE001595 Accident Date : 18/12/2021

Vehicle No : GBJ-3418-H Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO DETACH & RENEW REVERSE SENSOR	60.00	X
	Sub Total	1895.00	

Remarks:

5,897.15

SUB TOTAL
GST 7.0 % 412.80
TOTAL 6,309.95

Surveyor's name: _____

Principal's name: ETHOZ Group Ltd

Survey Date & Time: _____