



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 3141C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER - LH (CONSISTENT)	BADLY DENTED	589.60	589.60
1	FRONT FENDER DUST COVER - LH (CONSISTENT)	SERVICEABLE	102.20	-
6	FRONT FENDER DUST COVER CLIP - LH @\$5.50 (CONSISTENT)	NOT NECESSARY	33.00	-
1	FRONT DOOR - LH (CONSISTENT)	DENTED / BENT	986.40	986.40
1	FRONT DOOR RUBBER - LH (CONSISTENT)	NOT NECESSARY	289.40	-
1	FRONT DOOR HINGE LOWER - LH (CONSISTENT)	SERVICEABLE	56.20	-
	LESS 25% DISCOUNT		-514.20	-394.00
			1,542.60	1,182.00
	<u>LABOUR</u>			
	PANEL BEATING.		550.00	280.00
	TO REMOVE & REFIX DOOR ACCESSORY.		80.00	60.00
	TO SPRAY PAINTING.		620.00	400.00
			1,250.00	740.00
	GRAND TOTAL		2,792.60	1,922.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,500.00

Report Ref No. CC4/ASM22002522/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.