

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/GRB22002523/RPA3Q2  
**Date:** 26/10/2022

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447_01
<b>Claimant Vehicle No :</b>	YQ4802R	<b>Insured Vehicle No :</b>	SND1072Z
Date of Loss:	12/03/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0001545

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>YQ4802R</b>	Engine No:	1GD8807307
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JHHAGV46X0K001136
Reg. Date:	08/11/2021 (Man. Year: 2021)	Odometer:	23890 km
Colour:	Grey		
Engine Capacity:	2755 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/75 R15	Rear Tyre Size:	145/80 R13 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 5/5 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 5/5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,389.19	1,922.62	1,466.57	43.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	580.00	1,420.00	71.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,389.19</b>	<b>2,502.62</b>	<b>2,886.57</b>	<b>53.56</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,389.19</b>	<b>2,000.00</b>	<b>3,389.19</b>	<b>62.89</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>2,507.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,500.00</b>		

### INSPECTION

Date of Assignment:	16/03/2022	Ark Oto (HQ)
Date Inspected:	18/03/2022 Inspected At:	Blk 10 Ang Mo Kio Industrial Park 2A, #04-01 AMK Autopoint Singapore 568047
Estimated Period of Repair:	4.0 days	

---

**Adjuster:** MOHD RASUL

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 Oct 2022)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YQ4802R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT RIGHT SIDE AIR CLEANER BOX	Cracked	689.90 F	*689.90 FL
2	1	*FRONT RIGHT SIDE AIR CLEANER BOX HOLDER	Serviceable	283.90 F	*- FL
3	1	*FRONT RIGHT SIDE FENDER COWLING	Scratched	169.90 F	*169.90 FL
4	1	*FRONT RIGHT SIDE FENDER COWLING MUDFLAP	Serviceable	69.90 F	*- FL
5	1	*FRONT RIGHT SIDE CORNER BRACKET FRAME (TRIANGLE)	Repair	115.39 F	*- FL
6	1	*DIESEL TANK	Bent	1,189.90 F	*1,189.90 FL
7	1	*DIESEL TANK BRACKET HOLDER	Not Necessary	299.60 F	*- FL
8	1	*RIGHT SIDE PROTECTOR BAR	Bent	456.90 F	*456.90 FL
9	2	*RIGHT SIDE PROTECTOR BAR CORNER GARNISH	Scratched (1 PCS ONLY)	113.80 F	*56.90 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,389.19</b>	<b>2,563.50</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$)</b>	0.00	640.88
<b>Total Parts (\$)</b>	<b>3,389.19</b>	<b>1,922.62</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO SPRAY ANTI-RUST COATING ON NEW & AFFECTED PANELS	New	200.00	0.00
2	TO STRAIGHTEN ,REPAIR ,REALIGN ON AFFECTED AREA AND REPLACE THE ABOVE DAMAGED PARTS	New	900.00	400.00
3	TO RESPRAY PAINTING ON AFFECTED AREA	New	600.00	100.00
4	TO DISMANTLE & REPLACE DIESEL TANK	New	300.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,000.00</b>	<b>580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >