

Vehicle Damage Assessment Report for [YQ4802R]

Estimate Created: 28/09/2022 13:21 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 30/09/2022 05:35 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Hilux
Engine Type	1KDFTV		
License Plate Number	YQ4802R	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review based on the information provided by ARK OTO: Concluded lump sum repair cost of \$2000 with 3 working days.

Insurlogic 4 (30/09/2022 05:34)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT RIGHT SIDE AIR CLEANER BOX		1	689.90	-25.00 %	517.43
FRONT RIGHT SIDE FENDER COWLING		1	169.90	-25.00 %	127.43
DIESEL TANK		1	1189.90	-25.00 %	892.43
RIGHT SIDE PROTECTOR BAR		1	456.90	-25.00 %	342.68
RIGHT SIDE PROTECTOR BAR CORNER GARNISH		1	56.90	-25.00 %	42.68
Parts Subtotal					1,922.65

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREAS AND REPLACE THE ABOVE DAMAGED PARTS	RnR	400.00	0.00 %	400.00
TO DISMANTLE AND REPLACE DIESEL TANK	RnR	80.00	0.00 %	80.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price	
RESPRAY ON AFFECTED AREA	Full spray	99.99	0.00 %	99.99	
Labor Rate	S\$ 50 / Hour	General Labor Subtotal		480.00	
				Paint Labor Subtotal	99.99
				Labor Subtotal	579.99

Summary

Repair Cost	2,502.64
Discount(20 %)	(502.61)
	2,000.03
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	2,000.03