

## **LKK Auto Consultants Pte Ltd**

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 4774M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED / TORN	1,085.55	1,085.55
1	REAR BUMPER LOWER SKIRTING	GRAZED	398.05	398.05
2	REAR BUMPER SIDE RETAINERS @\$53.00	NECESSARY	106.00	106.00
2	REAR BUMPER PDC SENSORS @\$185.00	SERVICEABLE	370.00	-
1	REAR BUMPER BEAM	DENTED	555.95	555.95
1	REAR BUMPER TOP RETAINER	CRACKED	112.00	112.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	793.75	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	182.65	-
	LESS 5% DISCOUNT		-180.20	-112.88
			3,423.75	2,144.67
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR LICENCE PLATE (SN)	CRACKED	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
			150.00	90.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	30.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	100.00
	TO DIAGNOSTIC & REPROGRAMME SYSTEM.		180.00	180.00
	TO SPRAY RUST PROOFING.		50.00	30.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		680.00	580.00
	TO PUTTY & SPRAY PAINTING.		800.00	680.00
			1,960.00	1,650.00
	GRAND TOTAL		5,533.75	3,884.67

Report Ref No. CS/TP22002528/Uty3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,100.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/TP22002528/Uty3e2

CHUA KANG SENG

**Licensed Appraiser**