

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG22002535/RGA3Q2**Date:** 10/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700043792
Claimant Vehicle No :	SKF7454R	Insured Vehicle No :	SLR9247J
Date of Loss:	12/03/2022	Nature of Claim:	TP
		Claim No:	7741961344SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF7454R		
Make & Model:	KIA CERATO FORTE KOUP, 1.6 SX ABS D/AB SR (A)	Engine No:	G4FCCH247412
Reg. Date:	29/06/2012 (Man. Year: 2012)	Chassis No:	KNAFW611MC5634586
Colour:	Blue	Odometer:	88536 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	General 6 mm	Rear Left Side:	General 6 mm
Front Right Side:	General 6 mm	Rear Right Side:	General 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,436.00	381.20	1,054.80	73.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	1,860.00	1,170.00	38.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,466.00	2,241.20	2,224.80	49.82
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	4,466.00	2,000.00	2,466.00	55.22
+ GST 7.00/7.00% (S\$)	312.62	140.00	172.62	55.22
Nett Amount (S\$)	4,778.62	2,140.00	2,638.62	55.22
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
		2,675.00		

INSPECTION

Date of Assignment:	18/03/2022	
Date Inspected:	18/04/2022	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-RR BUMPER,CTR	Deformed	439.00 FS	*351.20 FS
2	1		*RAIL ASSY-REAR BUMPER	Not Necessary	559.00 FS	*- FS
3	1		*SENSOR ASSY-ULTRASONIC,BWS,CTR	Not Necessary	204.00 FS	*- FS
4	1		*SENSOR ASSY-ULTRASONIC,BWS,CTR	Not Necessary	204.00 FS	*- FS
5	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
					Total Parts (\$)	1,436.00 381.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RESPRAY REAR BUMPER,REAR END PANEL,REAR BODY KIT	New	1,400.00	700.00
2	RENEW REAR BUMPER,REPAIR BODY KIT,REAR END PANEL	New	1,200.00	800.00
3	REMOVE AND INSTALL REVERSE SENSOR TO FACILITATE REPAIRS	New	150.00	80.00
4	SUPPLY NUMBER PLATE WITH FRAME	New	50.00	50.00
5	APPLICATION TO BREAK AND RESEAL OPC PLATE	New	80.00	80.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
Gross Labour Cost (\$)			3,030.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >