

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002539/KTY3N2**Date:** 06/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00076832101

Claimant Vehicle No : SMA5282K **Insured Vehicle No :** GW4766T

Date of Loss: 15/03/2022 Nature of Claim: TP Claim No: SNM22D201826/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA5282K**

Make & Model: HYUNDAI ACCENT, 1.4 (A) Engine No: G4LCJU993944

Reg. Date: 12/06/2018 (Man. Year: 2018) Chassis No: KMHCU41BTJU431563

Colour: Metallic Black Odometer: 53704 km

Engine Capacity: 1368 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70R14 Rear Tyre Size: 175/70R14

Front Left Side: Falken 7 mm Rear Left Side: Falken 7 mm

Front Right Side: Falken 7 mm Rear Right Side: Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	350.00	310.00	40.00	11.43
Miscellaneous Items	100.00	100.00	0.00	0.00
Labour	50.40	50.40	0.00	0.00
Paintwork Labour	262.04	262.04	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	762.44	722.44	40.00	5.25
+ GST 7.00/7.00% (S\$)	53.37	50.57	2.80	5.25
Nett Amount (S\$)	815.81	773.01	42.80	5.25

INSPECTION

Date of Assignment: 18/03/2022 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Date Inspected: 04/04/2022 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2022)
Parts:	144	HYUNDAI ACCENT 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA5282K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		350.00 F	*310.00 F
F=Franchise part.						
				Total Parts (S\$)	350.00	310.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Extra	100.00	100.00
Sub Total (\$\$)			100.00	100.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Including Material	New	262.04	262.04
<u>Labour Items</u>				
2	Total of Labour	New	50.40	50.40
Gross Labour Cost (\$\$)			312.44	312.44

Report was unsubmitted during this print-out.

< END OF ESTIMATES >