

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002540/EQY3N2**Date:** 05/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00016162201		
Claimant Vehicle No :	SGD7175D	Insured Vehicle No :	GBD2168S		
Date of Loss:	16/03/2022	Nature of Claim:	TP	Claim No:	SNM22D201853/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGD7175D		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	1ZZ2476079
Reg. Date:	22/02/2006 (Man. Year: 2006)	Chassis No:	ZNE100287383
Colour:	White	Odometer:	266364 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,073.75	6,177.50	3,896.25	38.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,960.00	710.00	26.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,743.75	8,137.50	4,606.25	36.15
Approved Total (Overridden) (\$\$)		6,500.00		
(\$\$)	12,743.75	6,500.00	6,243.75	48.99
+ GST 7.00/7.00% (\$\$)	892.06	455.00	437.06	48.99
Nett Amount (\$\$)	13,635.81	6,955.00	6,680.81	48.99

INSPECTION

Date of Assignment:	18/03/2022		
Date Inspected:	18/03/2022	Inspected At:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair:	5.0 days		

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGD7175D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Broken	1,219.00 FL	*1,219.00 FL
2	1		*BOOT LID	Dented	1,719.00 FL	*1,208.00 FL
3	1		*BOOT LID LOCK	Bent	579.00 FL	*220.00 FL
4	1		*BOOT LID TRIM BOARD	Crushed	790.00 FL	*680.00 FL
5	1		*BOOT LID LOGO BADGE	Necessary	231.00 FL	*70.00 FL
6	1		*BOOT LID OUTER CENTER CHROME	Broken	471.00 FL	*383.00 FL
7	1		*BOOT LID EMBLEM DRIVE	Necessary	62.00 FL	*62.00 FL
8	1		*BOOT LID TOP SPOILER BRAKE LAMP	Broken	579.00 FL	*233.00 FL
9	2		*BOOT LID BOTH HINGE LH/RH	Not Necessary	462.00 FL	*- FL
10	1		*BOOT LID WEATHERSTRIP	Crushed	371.00 FL	*300.00 FL
11	1		*TAIL LAMP RH	Broken	579.00 FL	*472.00 FL
12	1		*REAR BUMPER	Dented	481.00 FL	*481.00 FL
13	1		*REAR BUMPER SIDE RETAINER LH/RH (2 Pcs)	Broken (1 Pc only)	462.00 FL	*110.00 FL
14	1		*REAR BUMPER SIDE REFLECTOR LH/RH (2 Pcs)	Broken (1 Pc only)	382.00 FL	*124.00 FL
15	1		*END PANEL	Dented	790.00 FL	*590.00 FL
16	1		*END PANEL SIDE BRACKET METAL LH/RH (2 Pcs)	Dented (1 Pc only)	342.00 FL	*88.00 FL
17	1		*END PANEL TOP GARNISH	Crushed	402.00 FL	*230.00 FL
18	2		*REAR CAR PLATE LAMP LH/RH	Not Necessary	244.00 FL	*- FL
19	1		*REAR BOOT LID LOCK SWITCH	Not Necessary	180.00 FS	*- FS
20	1		*BOOT LID TOP SPOILER	Broken	1,200.00 FS	*600.00 FS
21	3		*REAR WINDSCREEN MOULDING	Necessary	180.00 FS	*120.00 FS
22	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
23	1		*REAR CARPLATE	Cut	35.00 FS	*35.00 FS
24	1		*REAR REVERSE SENSOR	Broken	200.00 FS	*200.00 FS
25	1		*END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS
26	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
27	1		*REAR WINDSCREEN SOLAR FILM	Necessary	200.00 FS	*100.00 FS
28	1		*REAR BUMPER LOWER CHROME STRIPE	Necessary	100.00 FS	*70.00 FS
29	1		*BOOT LID EMBLEM CHINESE WORD)	Necessary	100.00 FS	*50.00 FS
30	1		*BOOT LID EMBLEM BLUE	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,615.00	7,795.00
- List Item Discount on L Items 25.00/25.00% (S\$)	2,541.25	1,617.50
Total Parts (S\$)	10,073.75	6,177.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,200.00	900.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,000.00	800.00
3	TO REMOVE/REFIX/REPLACE WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	60.00	30.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	60.00	30.00
5	TO REMOVE AND REFIT/REPLACE REAR COMPARTMENT FITTING,TRIMMINGS,GARNISH AND ETC	New	100.00	50.00
6	TO REMOVE AND REPLACE REAR WINDSCREEN	New	150.00	120.00
7	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	100.00	30.00
Gross Labour Cost (\$\$)			2,670.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >