

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002541/ATY3S2**Date:** 24/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00153512101
Claimant Vehicle No :	GX5822C	Insured Vehicle No :	YN9698H
Date of Loss:	12/02/2022	Nature of Claim:	TP
		Claim No:	SNM22D201139/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX5822C	Engine No:	5L5433892
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	LY2300009836
Reg. Date:	10/07/2004 (Man. Year: 2004)	Odometer:	372759 km
Colour:	Blue		
Engine Capacity:	2985 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	165 R13C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Maxmiller 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Maxmiller 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,681.70	3,836.32	3,845.38	50.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,290.00	860.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,831.70	5,126.32	4,705.38	47.86
Approved Total (Overridden) (\$\$)		4,100.00		
Nett Amount (\$\$)	9,831.70	4,100.00	5,731.70	58.30

INSPECTION

Date of Assignment:	20/03/2022	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Date Inspected:	22/03/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 May 2022)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX5822C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH SIDE GATE	Dented	1,409.20 FL	*1,409.20 FL
2	6		*LH SIDE GATE HINGES	Not Necessary	346.20 FL	*- FL
3	1		*LH SIDE GATE OPENER HANDLE	Dented	139.00 FL	*139.00 FL
4	1		*REAR LH RUBBER STOPPER	Not Necessary	43.10 FL	*- FL
5	1		*REAR LH RUBBER STOPPER BRACKET	Not Necessary	98.60 FL	*- FL
6	1		*REAR LH TAILLAMP	Cracked	251.30 FL	*251.30 FL
7	1		*REAR LH TAILLAMP BRACKET	Not Necessary	61.80 FL	*- FL
8	1		*REAR TAILGATE	Dented	1,116.70 FL	*1,116.70 FL
9	1		*REAR TAILGATE TOYOTA STICKER	Necessary	238.90 FL	*238.90 FL
10	4		*REAR TAILGATE HINGES	Not Necessary	230.80 FL	*- FL
11	1		*SET ALUMINIUM SWING DOOR REPAIR KIT	Necessary	200.00 FS	*150.00 FS
12	1		*CANOPY SILICON	Necessary	100.00 FS	*100.00 FS
13	1		*REAR ALUMINIUM SWING DOOR CANVAS	Not Necessary	500.00 FS	*- FS
14	1		*REAR LH ALUMINIUM DOOR	Dented	1,800.00 FS	*700.00 FS
15	1		*REAR LH ALUMINIUM SWING DOOR	Repair	1,300.00 FS	*- FS
16	1		*REAR LH SWING DOOR PILLAR	Dented	600.00 FS	*400.00 FS
17	1		*REAR TAILGATE 4I AX STICKER	Necessary	25.00 FS	*10.00 FS
18	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*10.00 FS
19	1		*REAR TAILGATE LTA SIGN STICKER	Necessary	180.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,665.60	4,625.10
- List Item Discount on L Items 25.00/25.00% (\$)	983.90	788.78
Total Parts (\$)	7,681.70	3,836.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING. (TO FR)	New	50.00	30.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	1,000.00	600.00
3	TO PROVIDE LABOUR, WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,000.00	600.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	100.00	60.00
Gross Labour Cost (S\$)			2,150.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >