

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22002542/GQY3N2**Date:** 10/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00038122100
<b>Claimant Vehicle No :</b>	SKN7346C	<b>Insured Vehicle No :</b>	GBE139J
Date of Loss:	17/03/2022	Nature of Claim:	TP
		Claim No:	SNM22D201877/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKN7346C</b>	Engine No:	PE20516677
Make & Model:	MAZDA 6, 2.0 (A)	Chassis No:	JM6GJ1071E0139147
Reg. Date:	14/07/2014 (Man. Year: 2014)	Odometer:	154991 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/50ZR18	Rear Tyre Size:	235/50ZR18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,915.76	1,050.08	1,865.68	63.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	1,340.00	780.00	36.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,035.76</b>	<b>2,390.08</b>	<b>2,645.68</b>	<b>52.54</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,900.00</b>		
<b>(\$\$)</b>	5,035.76	1,900.00	3,135.76	62.27
<b>+ GST 7.00/7.00% (\$\$)</b>	352.50	133.00	219.50	62.27
<b>Nett Amount (\$\$)</b>	<b>5,388.26</b>	<b>2,033.00</b>	<b>3,355.26</b>	<b>62.27</b>

**INSPECTION**

Date of Assignment:	18/03/2022	
Date Inspected:	28/04/2022 Inspected At:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	5.0 days	

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2022)
<b>Parts:</b>	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKN7346C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,231.50 FL	*- FL
2	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	41.00 FL	*- FL
3	1		*REAR BUMPER SPLASH SHIELD RH	Not Necessary	53.90 FL	*- FL
4	6		*REAR BUMPER CLIPS	Not Necessary	30.00 FL	*- FL
5	1		*REAR FENDER RH	Buckled	1,312.50 FL	*1,120.50 FL
6	1		*REAR FENDER MUDGUARD RH	Not Necessary	188.40 FL	*- FL
7	8		*REAR FENDER MUDGUARD CLIPS	Not Necessary	40.00 FL	*- FL
8	1		*REAR AIR VENT RH	Not Necessary	74.90 FL	*- FL
9	1		*REAR WINDSCREEN MLDG	Necessary	117.10 FL	*117.10 FL
10	1		*REAR WHEEL BEARING+ HUB RH	Not Necessary	480.40 FL	*- FL
11	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
12	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
13	1		*SPORT RIM RHR (NPA)	Not Necessary	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,629.70</b>	<b>1,297.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	713.94	247.52
<b>Total Parts (\$)</b>	<b>2,915.76</b>	<b>1,050.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	60.00
2	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REINSTALL CUSHIONS,SEATS,BACKREST,INNER TRIM,GARNISH,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	180.00	60.00
4	TO DISMANTLE,REPLACE AND REINSTALL UNDERCARRIAGE	New	120.00	0.00
5	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS	New	60.00	40.00
6	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	60.00
7	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER RH.TO KNOCK & REPAIR REAR FENDER INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	800.00	600.00
8	TO SPRAY REAR BUMPER,REAR FENDER RH.REAR FENDER INNER RH	New	700.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,120.00</b>	<b>1,340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >