



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 9294T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR DOOR LH (WCP)	BENT	1,180.00	1,180.00
1	REAR FENDER LH (WCP)	BENT	1,700.00	1,700.00
1	SIDE SKIRT LH (WCP)	DENTED / DISTORTED	410.00	410.00
1	SIDE SKIRT REAR RETAINER LH (WCP)	NECESSARY	26.00	26.00
1	REAR FENDER INNER SHIELD LH (WCP)	CRACKED	155.00	155.00
1	REAR DOOR WEATHERSTRIP LH (WCP) (ADDITIONAL)	NECESSARY	145.00	145.00
	COST PLUS 15%		542.40	542.40
			4,158.40	4,158.40
	<b><u>LABOUR</u></b>			
	TO CHECK / CLEAR FAULT CODES.		120.00	100.00
	TO REMOVE & REFIX REAR CUSHION ASSY.		80.00	80.00
	TO CUT + WELD, TO KNOCK DENTS ON INNER REINFORCE ROCKER PANEL LH AND RENEW OF PARTS.		800.00	700.00
	TO SPRAY PAINT (INCLUDING BLENDING FRONT DOOR LH + ROOF SIDE PANEL LH)		1,000.00	800.00
			2,000.00	1,680.00
	<b>GRAND TOTAL</b>		<b>6,158.40</b>	<b>5,838.40</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>5,838.40</b>
	<b>LESS EXCESS</b>			<b>-500.00</b>
	<b>NETT LIABILITY</b>			<b>5,338.40</b>

Report Ref No. CS/LPC22002544/Kty3s2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.