

Your Ref: -

Date: 26<sup>th</sup> July 2022

Our Ref: CS1/SCD22002547/Rqy3e2

**M/s Singapore Civil Defence Force (MHA05)**

91 Ubi Ave 4

Singapore 408827

(The Motor Claims Department)

Attn: Ralf Tay Gim Chye

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLW 676L**

**INSURED VEHICLE: QX 1253C**

**ACCIDENT DATE: 25/11/2021**

We thank you for your instruction on 18/03/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLW 676L from M/s Kah Motor Co. Sdn. Bhd.
- b) Final Repair Bill of SLW 676L from M/s Kah Motor Co. Sdn. Bhd.
- c) Singapore Accident Statement and Police Report of Vehicles SLW 676L.
- d) Colour damaged vehicle photographs of SLW 676L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLW 676L
Make & Model	: Honda Jazz 1.3 CVT
Chassis Number	: JHMGK3850JX204683
Year of Registration	: 2018
Engine Capacity	: 1318 cc

- 2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## OPINION ON REPAIR COST FOR VEHICLE NO. SLW 676L

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
1	SUNDRIES (SN)	NECESSARY	50.00
1	PANEL COMP, L.RR.DOOR (SN)	BENT	573.90
1	PANEL SET,L.RR.OUTSIDE (SN)	BENT	430.12
1	GLASS,L.QUARTER (SN)	NECESSARY	122.85
1	SPACER.L.RR.BUMPER SIDE (SN)	NECESSARY	13.50
1	WHEEL,DISK AL 15X7 (SN)	SCRATCHED	358.27
2	RUBBERRR QTR W/SHIELD (SN)	NECESSARY	15.45
1	CLIPQUARTER WINDSHIELD A (SN)	NECESSARY	2.92
1	CLIPQUARTER WINDSHIELD B (SN)	NECESSARY	2.92
1	CLIPQUARTER WINDSHIELD C (SN)	NECESSARY	1.95
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00
1	TAPEL.RR.DOOR SASH (SN)	NECESSARY	11.55
			1,643.43
	<b><u>LABOUR</u></b>		
	REMOVE & RE-INSTALL REVERSE SENSORS - 4PCS.		180.00
	SEALANT FOR LHR DOOR.		120.00
	SEALANT FOR LHR FENDER.		120.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.		180.00
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.		650.00
	REMOVE & INSTALL FUEL TANK FUEL PIPES.		650.00
	REMOVE & INSTALL RR.L QTR GLASS.		380.00
	WINDSCREEN DAM KIT.		100.00
	CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.		3,250.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION.		2,080.00
	WHEEL ALIGNMENT X4.		180.00
			7,890.00
	<b>GRAND TOTAL</b>		<b>9,533.43</b>

Report Ref No. CS1/SCD22002547/Rqy3e2



<b>RECOMMENDED COST OF REPAIRS</b>	<b>9,533.43</b>
------------------------------------	-----------------

Report Ref No. CS1/SCD22002547/Rqy3e2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.**