

REF: CS1/SCD22002547/Rqy3

Special Instruction:

From (Person): RALF TAY GIM CHYE of SCDF Date/Time: 18/03/2022
Estimated Cost: _____ Bill to: _____

LS : 9772.77 / ? DAYS

Third Parties:

Claimant:

Surveyor:

Workshop: KAH MOTOR.CO.SDN.BHD

OD/TP Re-inspection	Evaluation
1. Inspect the OD/TP for any visible damage or wear. 2. Check the OD/TP for any leaks or abnormal sounds. 3. Verify the OD/TP is properly secured and aligned. 4. Record the inspection results.	1. Evaluate the condition of the OD/TP. 2. Determine if the OD/TP is safe for use. 3. If necessary, schedule for repair or replacement. 4. Document the evaluation findings.

To Inspect Vehicle No: SLW 676L Insured: QX 1253C

at Workshop m/s KAH MOTOR CO.SDN.BHD

of 6A MANDAI ESTATE SINGAPORE 729903

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____
(Client's Record) _____ D.O.A. 25/11/2021

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 18/07/22 Confirmed with Final Fig _____, ____ days (Red \$ ____/____%; Original 7 ____ days)

Date/Time: 18/07/22 Submit Final Fig \$9533.43, 7 days (Red \$ 0 / 0 %; Original 7 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time 18/07/22 File Pass to Typist

3) Date/Time _____ File Pass to _____

5) Date/Time _____ File Pass to _____

2) Date/Time

4) Date/Time

6) Date/Time

File Return to

File Return to

File Return to