

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/GRB21008473/GVY3E2-1

**Date:** 16/04/2022

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MFL2021D0003327

**Claimant Vehicle No :** SLL6688X

**Insured Vehicle No :** SLJ7951P

Date of Loss: 03/08/2021

Nature of Claim: TP

Claim No: MFL2021D0003327

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL6688X**

Make & Model: MERCEDES-BENZ GLC 250, 2.0 4MATIC (A)

Engine No: 27492030697139

Reg. Date: 15/11/2016 (Man. Year: 2016)

Chassis No: WDC2539462F100187

Colour: Grey

Odometer: 115810 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/55 R19

Rear Tyre Size: 235/55 R19

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,262.25	3,899.62	8,362.63	68.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	1,290.00	2,250.00	63.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,802.25</b>	<b>5,189.62</b>	<b>10,612.63</b>	<b>67.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,150.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,802.25</b>	<b>4,150.00</b>	<b>11,652.25</b>	<b>73.74</b>

### INSPECTION

Date of Assignment: 18/03/2022

Date Inspected: 13/08/2021 Inspected At:

D Motorwerkz Pte Ltd (HQ)  
NO. 280 Woodlands Industrial E5, #01-03 Harvest  
@ Woodlands  
Singapore 757322

Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2022)
Parts:	M1-SUV	MERCEDES-BENZ GLC 250 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL6688X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Damaged	940.00 F	*940.00 FN
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	795.00 F	*- FN
3	1		*REAR BUMPER SIDE RETAINER	Damaged	148.00 F	*105.00 FN
4	2		*REAR BUMPER SENSORS	Serviceable	390.00 F	*- FN
5	1		*REAR BUMPER LOWER GARNISH	Damaged	545.00 F	*490.00 FN
6	1		*REAR FENDER	Repair	3,390.00 F	*- FN
7	1		*REAR FENDER ARCH GARNISH	Damaged	240.00 F	*240.00 FN
8	1		*REAR FENDER QUARTER GLASS MOULDING	Serviceable	442.00 F	*- FN
9	1		*REAR SPORT RIM (ORIGINAL AMG)	Damaged	2,291.25 F	*2,291.25 FN
10	1		*REAR WHEEL HUB BEARING	Serviceable	238.00 F	*- FN
11	1		*REAR KNUCKLE ARM	Serviceable	1,615.00 F	*- FN
12	1		*REAR LOWER ARM	Serviceable	245.00 F	*- FN
13	1		*REAR SHOCK ABSORBER	Serviceable	583.00 F	*- FN
14	1		*REAR TYRE (DEPRECIATION)	Damaged	400.00 FS	*240.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	12,262.25	4,306.25
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	406.63
Total Parts (\$\$)	12,262.25	3,899.62

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS	New	50.00	30.00
2	TO REMOVE AND REFIT REAR CUSHION SEATS, RADIO SPEAKER BOARD, INTERIOR UPHOLSTERY TO FACILITATE THE REPAIRS	New	200.00	60.00
3	TO REMOVE AND REFIT FUEL TANK SYSTEM	New	120.00	0.00
4	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	180.00	40.00
5	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	400.00	0.00
6	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT	New	200.00	60.00
7	TO REMOVE AND REFIT QUARTER GLASS TO FACILITATE THE REPAIRS	New	180.00	0.00
8	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,100.00	600.00
9	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,000.00	500.00
10	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	110.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,540.00</b>	<b>1,290.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >