

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006038/AKA3S2
Date: 24/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100453348
Claimant Vehicle No: SMR4525C Insured Vehicle No: SKR7567K
Date of Loss: 28/05/2020 Nature of Claim: TP Claim No: 0789394729SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMR4525C
Make & Model: MERCEDES-BENZ GLC 250, 2.0 4MATIC (A) Engine No: 27492030950637
Reg. Date: 28/11/2017 (Man. Year: 2016) Chassis No: WDC2539462F210071
Colour: White Odometer: 22719 km
Engine Capacity: 1991 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	55,948.70	9,518.10	46,430.60	82.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,990.00	790.00	10,200.00	92.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	66,938.70	10,308.10	56,630.60	84.60
Approved Total (Overridden) (S\$)		8,200.00		
(S\$)	66,938.70	8,200.00	58,738.70	87.75
+ GST 7.00/7.00% (S\$)	4,685.71	574.00	4,111.71	87.75
Nett Amount (S\$)	71,624.41	8,774.00	62,850.41	87.75

INSPECTION

Date of Assignment: 29/05/2020
Date Inspected: 01/06/2020 Inspected At: Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT
Singapore 415875
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (UPPER)	Deformed	2,196.00 FL	*2,196.00 FL
2	1		*FRONT BUMPER (LOWER)	Deformed	856.00 FL	*856.00 FL
3	1		*FRONT BUMPER FOGLAMP GARNISH RH	Not Necessary	95.00 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE (CENTER CHROME)	Not Necessary	396.00 FL	*- FL
5	2		*FRONT BUMPER LOWER GRILLE (SIDE CHROME)	Cracked	302.00 FL	*302.00 FL
6	1		*FRONT BUMPER SENSOR RH	Cracked 1pc Only	660.00 FL	*220.00 FL
		3pcs				
7	6		*FRONT BUMPER SENSOR HOLDER	Necessary	390.00 FL	*390.00 FL
8	1		*FRONT BUMPER SIDE RETAINER	O/s Necessary	296.00 FL	*148.00 FL
9	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	160.00 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	504.00 FL	*- FL
11	1		*FRONT BUMPER SPONGE	Cracked	198.00 FL	*198.00 FL
12	1		*HEAD LAMP RH	Cracked	3,528.00 FL	*3,528.00 FL
13	1		*HEAD LAMP LOWER BRACKET RH	Not Necessary	98.00 FL	*- FL
14	1		*HEAD LAMP SIDE BRACKET RH	Not Necessary	85.00 FL	*- FL
15	1		*FRONT FENDER RH	Repair	1,026.00 FL	*- FL
16	1		*FRONT FENDER ARCED GARNISH RH	Cut	277.00 FL	*277.00 FL
17	1		*FRONT FENDER COWLING RH (FRONT)	Not Necessary	213.00 FL	*- FL
18	1		*FRONT FENDER COWLING RH (REAR)	Not Necessary	156.00 FL	*- FL
19	1		*FRONT WHEEL RIM	O/s Cut	4,788.00 FL	*2,394.00 FL
20	2		*FRONT ABS SENSOR	Not Necessary	570.00 FL	*- FL
21	1		*FRONT STEERING RACK & PINION	Not Necessary	9,324.00 FL	*- FL
22	2		*FRONT WHEEL HUP WITH BEARING	Not Necessary	1,404.00 FL	*- FL
23	2		*FRONT SHOCK ABSORBER	Not Necessary	2,124.00 FL	*- FL
24	2		*FRONT KNUCKLE ARM	Not Necessary	2,880.00 FL	*- FL
25	2		*FRONT CASTER ARM	Not Necessary	1,908.00 FL	*- FL
26	2		*FRONT LOWER ARM	Not Necessary	1,656.00 FL	*- FL
27	2		*FRONT UPPER ARM	Not Necessary	1,886.00 FL	*- FL
28	2		*FRONT STABILIZER LINKAGE	Not Necessary	366.00 FL	*- FL
29	1		*REAR BUMPER TOP COVER CHROME	Not Necessary	376.00 FL	*- FL
30	1		*REAR BUMPER (UPPER)	Not Necessary	1,008.00 FL	*- FL
31	1		*REAR BUMPER (LOWER)	Not Necessary	727.00 FL	*- FL
32	1		*REAR BUMPER CHROME (CENTER)	Not Necessary	496.00 FL	*- FL
33	2		*REAR BUMPER REFLECTOR	Not Necessary	110.00 FL	*- FL
34	1		*REAR BUMPER TOWING COVER	Not Necessary	62.00 FL	*- FL
35	2		*REAR BUMPER EXHAUST CHROME	Not Necessary	794.00 FL	*- FL
36	2		*REAR BUMPER EXHAUST CHROME BRACKET	Not Necessary	306.00 FL	*- FL
37	4		*REAR BUMPER SENSOR	Not Necessary	876.00 FL	*- FL
38	6		*REAR BUMPER SENSOR HOLDER	Not Necessary	408.00 FL	*- FL
39	1		*REAR BUMPER SENSOR WIREHARNES	Not Necessary	896.00 FL	*- FL
40	2		*REAR BUMPER SIDE RETAINER	Not Necessary	310.00 FL	*- FL
41	2		*REAR BUMPER CENTER TOP BEAM	Not Necessary	336.00 FL	*- FL
42	1		*REAR BUMPER CENTER LOWER BEAM	Not Necessary	269.00 FL	*- FL
43	2		*REAR BUMPER LOWER BRACKET	Not Necessary	150.00 FL	*- FL
44	1		*REAR BUMPER REINFORCEMENT	Not Necessary	799.00 FL	*- FL
45	2		*TAILLAMP	Not Necessary	1,136.00 FL	*- FL
46	2		*TAILLAMP LOWER BRACKET	Not Necessary	304.00 FL	*- FL
47	2		*REAR FENDER COWLING	Not Necessary	394.00 FL	*- FL
48	2		*REAR WHEEL ARCED GARNISH	Not Necessary	556.00 FL	*- FL
49	1		*TAILGATE	Not Necessary	2,522.00 FL	*- FL
50	1		*TAILGATE LOGO	Not Necessary	84.00 FL	*- FL
51	1		*TAILGATE EMBLEM GLC	Not Necessary	96.00 FL	*- FL
52	1		*TAILGATE EMBLEM 250	Not Necessary	94.00 FL	*- FL
53	1		*TAILGATE EMBLEM 4MATIC	Not Necessary	125.00 FL	*- FL
54	1		*TAILGATE LOCK	Not Necessary	435.00 FL	*- FL
55	1		*TAILGATE FOOT SENSOR MODULE	Not Necessary	687.00 FL	*- FL

Report was unsubmitted during this print-out.